



12 South Center Street
Bensenville, IL 60106

Office: 630.350.3404
Fax: 630.350.3438
www.bensenville.il.us

VILLAGE BOARD

September 20, 2018

President
Frank DeSimone

Board of Trustees
Rosa Carmona
Ann Franz
Agnieszka "Annie" Jaworska
Melanie Lomax
Nicholas Pancola Jr.
Armando Perez

Village Clerk
Nancy Dunn

Village Manager
Evan K. Summers

Ms. Maureen Barr
133 North Jackson Street, 3rd Floor
Chicago, Illinois 60661

Re: September 18, 2018 FOIA Request

Dear Ms. Barr:

I am pleased to help you with your September 18, 2018 Freedom of Information Act ("FOIA"). The Village of Bensenville received your request on September 18, 2018. You requested copies of the items indicated below:

"Fire Department Records RE: 951-961 Thorndale Avenue."


After a search of Village files, the following documents are enclosed to fulfill your request:

- 1) Village of Bensenville Correction Notice for Inspection No. 18191. (2 pgs.)

These are all of the documents that can be discovered responsive to your request.

Please contact the Illinois Fire Marshal's Office in regards to UST/AST information.

Do not hesitate to contact me if you have any questions or concerns in connection with this response.

Very truly yours,

Corey Williamsen
Freedom of Information Officer
Village of Bensenville



**VILLAGE OF BENSENVILLE
INSPECTIONAL SERVICES**
12 South Center
Bensenville, IL 60106
630-350-3413 fax:630-350-3449

Type of Inspection: ANNUAL INSPECTION

CORRECTION NOTICE

Address: 951 THORNDALE Unit:

Business name:: PACTRAN AIR AND SEA Phone:

Business Owner: PACTRAN AIR AND SEA Address: 951-61 tHORNDALE AVE BENSENVILLE, IL

Inspection Date: 2/7/13 Inspector: TOM KNIGHT

<u>Checklist #</u>	<u>Violation</u>	<u>Violation comment</u>
030E	PARKING LOT NEEDS SEAL COATING	Sealcoat parking lot and driveway. Re-stripe parking spaces following sealcoating. Provide adequate handicap parking according to Illinois law.
040	EXTERIOR LANDING	Repair/replace exterior door sill (NW door).
050L	REPAIR CRACKS IN EXTERIOR WALLS	Repair cracks in exterior walls.
060	EXTERIOR DOOR	Repair/replace all exterior doors as needed. Rusted doors, headers, and frames must be repaired or replaced.
170C	SPRINKLER HEAD(S) NEEDED	Provide sprinkler protection under overhead dock doors.

Additional Remarks/Comments:

Created from inspection 17179 on
11/02/2012 by 6523tkni

Reinspection 20170 created on 02/07/2013
by 6523tkni

THOSE ITEMS LISTED ABOVE ARE VIOLATIONS OF BENSENVILLE'S ADOPTED VILLAGE CODE AND/OR PROPERTY MAINTENANCE CODE. THIS IS YOUR WRITTEN "CORRECTION NOTICE". FAILURE TO CORRECT THE ABOVE LISTED VIOLATIONS WITHIN THE PRESCRIBED TIME CAN RESULT IN A FINE OF UP TO \$750 PER VIOLATION, PER DAY.

You are hereby notified to remedy the conditions as stated above within 14 days from the date of this order. Appeal from this order may be made within 20 days from the above date of service. Direct such appeal for a hearing before the Bensenville Board of Appeals in writing through the Director of Inspectional Services, 12 South Center.

Neither this inspection nor any Certificate of Occupancy issued by the Village of Bensenville shall be considered a complete list of Code or Municipal Ordinances. Our inspection can be substantially limited by access available and stored items or furniture. Some occupancies may require inspections to be completed on individual systems such as heating appliances, roofing, structure or fire protection systems. If you have questions about this inspection, please call 630-350-3448.

DISCLAIMER: The Village of Bensenville does not warrant the condition of any property inspected and disclaims all liability for any claims arising out of the property or condition thereof.



VILLAGE OF BENSENVILLE

INSPECTORIAL SERVICES

12 South Center
Bensenville, IL 60106
630-350-3413 fax:630-350-3449

Type of Inspection: ANNUAL INSPECTION

CORRECTION NOTICE

Address: 951 THORNDALE Unit:

Business name:: PACTRAN AIR AND SEA Phone:

Business Owner: PACTRAN AIR AND SEA Address: 951-61 tHORNDALE AVE BENSENVILLE, IL

Inspection Date: 2/7/13 Inspector: TOM KNIGHT

Copy of this report received by/mailed to: _____

Inspector: _____ Date: _____