



12 South Center Street
Bensenville, IL 60006

Office: 630.350.3404
Fax: 630.350.3408
www.bensenville.il.us

VILLAGE BOARD

President

Frank DeSimone

Board of Trustees

Gusa Carmona

Ann Feunz

Marie J. Frey

Melanie Lomas

Humberto Paricela Jr.

Armando Perez

Village Clerk

Nancy Bunn

Village Manager

Evan K. Summers

September 16, 2020

Ms. Carrie Ortiz - TPI
325 Spruce Street
South Elgin, Illinois 60177

Re: September 14, 2020 Commercial FOIA Request

Dear Ms. Ortiz:

I am pleased to help you with your September 14, 2020 Commercial Freedom of Information Act ("FOIA"). The Village of Bensenville received your request on September 14, 2020. You requested copies of the items indicated below:

"1) Monthly invoices for the past twelve months from Safebuilt regarding building department services and fees. 2) RFP records from Safebuilt for the past 5 years building department."

After a search of Village files, the following documents are enclosed to fulfill your request:

- 1) Safebuilt Invoice from September 1, 2019 – August 1, 2020. (98 pgs.)
- 2) Safebuilt Proposal for Profession Residential, Mixed Use, and Commercial Plan Review & Inspection Services for Bensenville, Illinois dated September 18, 2015. (46 pgs.)


These are all of the documents that can be discovered responsive to your request.

Do not hesitate to contact me if you have any questions or concerns in connection with this response.

Very truly yours,

Corey Williamsen
Freedom of Information Officer
Village of Bensenville

SAFEbuilt®



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **08312019BENSNVL-2**
Issue Date **09/01/2019**
Due Date **10/01/2019 (Net 30)**
Subject **VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - AUGUST 2019**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 08/01/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 146 W. Irving Park Rd. Permit 9379 # 69340.	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/01/2019 - SFR Plumbing Inspection / Vince Cirone: 400 Spruce Permit 8289 # 68529 Rough plumbing underground	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/01/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 1057 S. York. Permit 9136 # 67830 Rough underground plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/02/2019 - SFR Mechanical Inspection / David DeLeon: 321 S Hawthorne - final 9229, 68180	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/02/2019 - SFR Electrical Inspection / David DeLeon: 321 S Hawthorne - final 9229, 68179	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/14/2019 - SFR Electrical Inspection / David DeLeon: 523 S Marshall - final 9284, 68630.	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/02/2019 - SFR Mechanical Inspection / David DeLeon: 523 S Marshall - final , 9284, 68631	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/14/2019 - SFR Building/Structural Inspection / David DeLeon: 149 E George - pre pour 9215, 69350	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/02/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 951 Thorndale - final 9278, 68450	1.00	\$43.75	\$43.75

10.7.19
REQUISITION # 20193737

Inspections	4000-CECHI-IL-BI - 08/07/2019 - SFR Building/Structural Inspection / Jurtin Vide: 202 s miner st- final membrane/water proofing Permit 9317. Inspection ID 68742	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/05/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce- NEW SFR foundation pre pour Permit 9289. Inspection ID 68522	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/05/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce- NEW SFR drain tile Permit 9289. Inspection ID 68527	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/07/2019 - SFR Building/Structural Inspection / Jurtin Vide: 143 e Daniel dr- final building patio Permit 9193. Inspection ID 67823	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/07/2019 - SFR Building/Structural Inspection / Jurtin Vide: 123 Jacquelyn dr- final building Permit 9107. Inspection ID 67274	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/07/2019 - SFR Electrical Inspection / Jurtin Vide: 123 Jacquelyn dr- final electric Permit. 9107. Inspection ID 67626	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/08/2019 - SFR Building/Structural Inspection / Reese Menard: 426 S. Judson Fence final permit 9114 inspection 67399	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/08/2019 - SFR Building/Structural Inspection / Reese Menard: 136 S. Church Rd. Final garage permit 9080 inspection 67042	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/08/2019 - SFR Building/Structural Inspection / Reese Menard: 400 N. Spruce Damp proof permit 9289 inspection 69455	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/08/2019 - SFR Electrical Inspection / Reese Menard: 136 S Church Rd. underground garage permit 9080 inspection 67074	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/08/2019 - SFR Electrical Inspection / Reese Menard: 136 S. Church Rd. electrical final garage permit 9080 inspection 67075	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/08/2019 - MFR/Commercial Plumbing Inspection / Reese Menard: 601-607 Country Club Dr. water main repair permit 9401 inspection 69493	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/09/2019 - SFR Plumbing Inspection / Vince Cirone: 142 Walnut Permit 9332 # 69082 Rough plumbing Approved	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 08/09/2019 - SFR Building/Structural Inspection / Vince Cirone: 142 S. Walnut Permit 9332 # 69083 Insulation	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/09/2019 - SFR Building/Structural Inspection / Vince Cirone: 142 S.Walnut Permit 9332 68870	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/09/2019 - SFR Electrical Inspection / Vince Cirone: 142 3 Walnut Permit 9332 # 69081 Rough Ele.	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/09/2019 - SFR Building/Structural Inspection / Vince Cirone: 157 Ellis Permit 9222 # 68068 Rough framing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/09/2019 - MFR/Commercial Building/Structural Inspection / Reese Menard: 877 N. Supreme Dr. Final structural racking, Permit 9285 Inspection 68497	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/12/2019 - SFR Building/Structural Inspection / Jurtin Vide: 445 s center- pier pre pour fence FAIL Permit 9254. Inspection ID 68306	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/12/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 640 e George st #D- rough framing Permit 8936. Inspection ID 65773	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/12/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce ave- basement slab pre pour Permit. 9289. Inspection ID 68525	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/12/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce - garage slab prepour Permit. 9289. Inspection ID 68853	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/12/2019 - SFR Building/Structural Inspection / Jurtin Vide: 445 s center st- piers pre pour fence REINSPECTION FROM AM FAIL Permit. 9254. Inspection ID 69604	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/13/2019 - SFR Building/Structural Inspection / Jurtin Vide: 800 w second ct- final fence Permit 9070. Inspection ID 67005	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/13/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 659 w supreme-basin adjustments Permit 9339. Inspection ID 69208	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 08/13/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 659 w supreme dr-pavement final Permit 9339. Inspection ID 69207	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/13/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1001 w foster ave-final building Permit 8763. Inspection ID 65430	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/13/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 630 w supreme-pavement final Permit 9343. Inspection 69215	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/13/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 630 w supreme-sewer adjustment Permit 9343. Inspection 69216	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/13/2019 - SFR Electrical Inspection / Jurtin Vide: 865 s Brentwood ct- NEW SFR electric service Permit 8899. Inspection ID 65311	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/14/2019 - SFR Plumbing Inspeccion / Vince Cirone: 344 S. Mason. Permit 8883 # 66845 Final Plumbing Approved	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/14/2019 - SFR Plumbing Inspeccion / Vince Cirone: 1044 S. Addison Permit 9349 # 69138 Flood Control Approved	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/14/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 13 W. GRAND AVE., FINAL - FIRE ALARM, 9062, 66882	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/14/2019 - SFR Electrical Inspection / David DeLeon: 344 S. MASON STREET, FINAL, 8883, 69568	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Building/Structural Inspection / David DeLeon: 865 S. BRENTWOOD CT, STOOP & SERVICEWALK PREPOUR 8899 65302	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Building/Structural Inspection / David DeLeon: 865 S. BRENTWOOD CT. PATIO PREPOUR, 8899 66638	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Building/Structural Inspection / David DeLeon: 865 S. BRENTWOOD CT. GARAGE FLOOR PREPOUR, 8899, 66639	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Building/Structural Inspection / David DeLeon: 834 S. CENTER ST., FINAL/ PATIO,9310 68712	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Building/Structural Inspection / David DeLeon: 344 S. Mason St., Final.8883 65168	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Building/Structural Inspection / David DeLeon: 609 W WOOD ST., Final / Patio,9151 67540	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 361 N. MARSHALL RD, OTHER: HOUSE WRAP 8814, 69664	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/15/2019 - MFR/Commercial Mechanical Inspection / David DeLeon: 701 W MAPLE LANE, FINAL MECH, 8947, 65928	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/15/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 701 W MAPLE LANE, FINAL, 8947, 65929	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/15/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 837 W. FAIRWAY DR., FINAL ELECTRIC,9281, 68474	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/15/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 701 W MAPLE LANE, FINAL, 8947, 65927	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Plumbing Inspection / Vince Cirone: 410 E. Jefferson Permit 8549 # 63179 Final plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - SFR Plumbing Inspection / Vince Cirone: 410 E Jefferson Permit 8549 # 63178 Final for water heater.	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/15/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 701 W. Maple Permit 8947 # 65926 Final plumbing complete	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/16/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 1061 S York Permit 8920 # 65641 Final plumbing Failed.	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 08/16/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 701 W. MAPLE LANE FINAL BLD, 8947, 69697	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/16/2019 - MFR/Commercial Mechanical Inspection / David DeLeon: 701 W. MAPLE LANE, FINAL MECH, 8947, 69696	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/16/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 701 W. MAPLE LANE, FINAL, 8947, 69698	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/16/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1061 S. YORK RD., FINAL, 8920, 65642	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/16/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1061 S. YORK RD., FINAL HVAC, 8920, 65643	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/16/2019 - SFR Building/Structural Inspection / David DeLeon: 210 S MINER ST., ROUGH FRAMING/ PORCH, 9242, 68225	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/19/2019 - SFR Building/Structural Inspection / Jurtin Vide: 344 s mason st- final building Permit 8893. Inspection ID 69699	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1061 s York rd- pre pour slab Permit 8920. Inspection ID 66690	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1057 s county line rd- pre pour piers Permit 8855. Inspection ID 64827	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1057 s York rd- rough framing Permit 9136. Inspection Id 67448	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1061 s York rd- final electric Permit 8920. Inspection ID 69739	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1057 s county line rd- rough electric Permit 9136. Inspection ID 67446	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 1061 S. York Rd. Final Plumbing Approved. Permit # 8920 # 69736	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/20/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 1057 S. York Rough Plumbing in walls with stack test. Approved Permit 9136 # 67449	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/21/2019 - SFR Building/Structural Inspection / Jurtin Vide: 426 s center st- final building Permit 9082. Inspection ID 67057	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/21/2019 - SFR Building/Structural Inspection / Jurtin Vide: 1044 s Addison st- final building Permit 9349. Inspection ID 68997	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/21/2019 - SFR Electrical Inspection / Jurtin Vide: 426 s center- final electric Permit 9082. Inspection ID 67127	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/21/2019 - SFR Electrical Inspection / Jurtin Vide: 1044 s Addison st- underground electric Permit 9349. Inspection ID 69137	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/21/2019 - SFR Electrical Inspection / Jurtin Vide: 1044 s Addison st- final electric Permit 9349. Inspection ID 69139	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/22/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 367 S. EVERGREEN ST. FIRE ALARM, 9313, 69100	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/22/2019 - SFR Building/Structural Inspection / David DeLeon: 231 E. JACQUELYN DR., POST HOLES / FENCE, 9145, 67500	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/23/2019 - MFR/Commercial Building/Structural Inspection / Vince Cirone: Plan Review per Dean 1004 W Irving Park	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/23/2019 - SFR Building/Structural Inspection / David DeLeon: 230 N. WALNUT ST. - A, PAVER BASE - PATIO 9096, 67257	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/23/2019 - SFR Building/Structural Inspection / David DeLeon: 231 E. JACQUELYN DR., POST HOLES / FENCE 9145, 69885	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 08/29/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: Plan Review Permit 9456 # 69971. 300 W Beeline Rd	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/30/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1208 W Irving Park - pre pour 9210, 68803	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 08/30/2019 - SFR Building/Structural Inspection / David DeLeon: 841 W Plentywood - piers 9432, 69749	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 08/30/2019 - SFR Building/Structural Inspection / David DeLeon: 1020 W Glendale - final building 9220, 68657	1.00	\$35.00	\$35.00

Amount Due \$3,797.50

OK
✓DL

Invoice



Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Terms: Net 30 Days

Due Date: 10/30/19

Salesperson: SNO

Customer Number: 06-BENSNVL

Customer P.O.:

09302019BENSNVL-1

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/03/2019 - MFR/Commercial Building/Structural Inspection / Jim Kemper: 1208 W. IRVING PARK RD. /PERMIT# 9120 /INSPECTION#70109 /CONCRETE PRE POUR	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/03/2019 - MFR/Commercial Building/Structural Inspection / Jim Kemper: 1050 S. COUNTY LINE RD. /PERMIT# 8855 /INSPECTION# 70117 /CONCRETE PRE POUR	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 860 THOMAS - ABOVE CEILING 9406, 69543	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 860 THOMAS - INSULATION 9406, 69658	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 COUNTY LINE - PRE POUR 8855, 70159	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/04/2019 - SFR Building/Structural Inspection / David DeLeon: 1009 BROOKWOOD - FRAMING 8629, 63375	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/04/2019 - SFR Building/Structural Inspection / David DeLeon: 216 MAY - PIERS 9438, 69883	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Electrical Inspection / David DeLeon: 400 SPRUCE - ELEC SERVICE 9289, 68533	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 227 W. GRAND AVE. FINAL BUILDING, 8960, 66096	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 227 W. GRAND AVE. FINAL, 8960, 66095	1.00	43.75	43.75

Continued

Requisition #2019 3138



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 2

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 227 W. GRAND AVE., FINAL, 8957, 66036	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 1221 W. ELMHURST ST., SLAB ON GRADE/ PATIO, 9226, 68251	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 329 S BARON - - FINAL 9157, 70165	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 1017 DONNA - FINAL FENCE 9164, 67769	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 747 S DENNIS - POST HOLES 9152, 67543	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 223 S MARION - FRAMING 9156, 67881	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 223 S MARION - FRAMING 9156, 67585	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 321 HAWTHORNE - FINAL 9229, 69700	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 438 COUNTY LINE RD - 7882, 68415	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Building/Structural Inspection / David DeLeon: 448 GRACE - FINAL PAVEMENT 9425, 69868	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 218 PARK - BASE 9372, 69411	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/05/2019 - SFR Plumbing Inspection / Walter Smith: 227 w grand Ave /Permit 8960 /ID 66094	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/06/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 130 S. George Unit 102. 9487, ID 70214	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/06/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 300 W. Beeline Plan Review	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/06/2019 - SFR Building/Structural Inspection / David DeLeon: 172 S Foley - pre pour 9304, 68664	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 3

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/06/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 300 W Beeline - Plan Review 2	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/09/2019 - SFR Building/Structural Inspection / David DeLeon: 401 E JEFFERSON - 9348, 69159	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/09/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 S COUNTY LINE RD - 8855, 70258	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/09/2019 - SFR Building/Structural Inspection / David DeLeon: 342 BARRON - FINAL 9405, 69590	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/09/2019 - SFR Building/Structural Inspection / David DeLeon: 157 ELLIS - FINAL BUILDING 9222, 68070	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1010 w foster-slab on grade /Permit 9292. Inspection ID 68723	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - SFR Building/Structural Inspection / Jurtin Vide: 1009 w brookwood- reinspection partial final on porch /Permit 8629. Inspection ID 70325	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce- NEW SFR service walk pre pour /PERMIT 9289. Inspection ID 68524	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - SFR Building/Structural Inspection / Jurtin Vide: 731 w main st- final shed /Permit 9437. Inspection ID 69790	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - SFR Building/Structural Inspection / Jurtin Vide: 106 E red oak st- concrete piers pre pour /Permit 9214. Inspection ID 68004	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - SFR Electrical Inspection / Jurtin Vide: 227 s Addison - final electric service /Permit 9442. Inspection ID 69972	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/10/2019 - SFR Electrical Inspection / Jurtin Vide: 1009 w brookwood- electric service /Permit 8629. Inspection ID 63240	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 361 Marshall rd- rough framing /Permit 8814. Inspection ID 64405	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - SFR Plumbing Inspection / Vince Cirone: 1050 Country Line Rd. Permit 8877 # 65081, Rough underground inspection with stack test	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 4

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - SFR Plumbing Inspeccion / Vince Cirone: 361 Marshall Permit 8814 # 65881. Rough plumbing with stack test	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - SFR Building/Structural Inspection / Jurtin Vide: 865 s Brentwood ct- NEW SFR rough mechanical /Permit 8899. Inspection ID 65319	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 spruce ave- NEW SFR house wrap /Permit 9289. Inspection ID 70334	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 133 e grand ave- concrete piers pre pour /Permit 9382. Inspection ID 69505	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/11/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 361 Marshall rd- rough electric partial /Permit 8814. Inspection ID 64403	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - SFR Plumbing Inspeccion / Ray Witkowski: 400 spruce /Rough plumbing /Permit: 8289 /Id: 68536	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - MFR/Commercial Plumbing Inspection / Ray Witkowski: 430 n York /Final plumbing /Permit: 8860 /Id: 64892	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 484 Thomas - piers 9474, 70166	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - SFR Building/Structural Inspection / David DeLeon: 244 S Miner - drain tile 9294, 69722	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - SFR Building/Structural Inspection / David DeLeon: 1181 Central - final 8983, 66373	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - SFR Building/Structural Inspection / David DeLeon: 216 S May - final 9438, 69884	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/12/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 736 Birginal - footing 9466, 70160	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/13/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 736 Birgindale - pre pour 9466, 70161	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 5

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/13/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 430 N York - final 8893, 65611	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/16/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1057 s York rd- drop ceiling mechanical /Permit 9136. ID 67444	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 117 w Belmont - final mechanical furnace/AC /Permit 9452. ID 70006	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 1308 w brookwood - slab on grade /Permit 9322. ID 69414	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 1308 brookwood- garage floor pre pour /Permit 9322. ID 68767	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/16/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1057 s York rd- drop ceiling /Permit 9136. ID 67445	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/16/2019 - SFR Electrical Inspection / Jurtin Vide: 117 w Belmont- final mechanical furnace and AC /Permit 9452. ID 7005	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/17/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 146 w Irving park- rough framing /Permit 9379. ID 69331	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/17/2019 - MFR/Commercial Plumbing Inspection / Jim Kemper: 147 (146) E. IRVING PARK RD. /ROUGH PLUMBING /PERMIT 9379 /INSPECTION 69330	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/17/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 736 n Birginal- slab on grade pre pour /Permit 9466. ID 70162	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/17/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1050 s county line rd- trench wall pre pour /Permit 8855. ID 70462	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/17/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 146 w Irving park- rough electric /Permit 9379. ID 69329	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 6

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/18/2019 - SFR Building/Structural Inspection / Jurtin Vide: 1308 w brookwood- concrete piers pre pour /Permit 9322 ID 69413	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/18/2019 - SFR Building/Structural Inspection / Jurtin Vide: 865 s Brentwood ct- NEW SFR fireplace firebox /Permit 8899 ID 70525	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/18/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 227 Grand - final 9054, 66820	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/18/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 227 Grand Ave - final 9054, 69483	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/18/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1208 W Irving Park service 9120, 68806	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/18/2019 - SFR Electrical Inspection / David DeLeon: 865 Brentwood - rough 8899, 65317	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/19/2019 - SFR Building/Structural Inspection / David DeLeon: 865 Brentwood - fireplace 8899, 70535	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/19/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 County Line Rd - pre pour - 8855, 70534	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/19/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 133 Grand Ave - final 9382, 69506	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/20/2019 - SFR Building/Structural Inspection / David DeLeon: 123 E JACQUELYN - BASE 9477, 70229	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/20/2019 - SFR Building/Structural Inspection / David DeLeon: 530 E RED OAK - PRE POUR 9439, 69798	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/20/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 S COUNTY LINE RD - PRE POUR 8855, 70588	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/20/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1225 DEVON - UG ELECTRIC 9428, 69829	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/20/2019 - SFR Electrical Inspection / David DeLeon: 235 MASON - ROUGH 9071, 67276	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/20/2019 - SFR Electrical Inspection / David DeLeon: 235 MASON - FINAL 9071, 67277	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 7

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Building/Structural Inspection / Jurtin Vide: 149 E George st- rough framing /Permit 9215. ID 68012	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Mechanical Inspection / Jurtin Vide: 149 e George- rough mechanical /Permit 9215. ID 68384	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Electrical Inspection / Jurtin Vide: 149 e George- rough electric /Permit 9215. ID 68010	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 N spruce- NEW SFR rough framing /Permit 9289. ID 68542	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Mechanical Inspection / Jurtin Vide: 400n spruce- NEW SFR rough mechanical /PERMIT 9289. ID 68549	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Electrical Inspection / Jurtin Vide: 400 n spruce- NEW SFR rough electric /Permit 9289. ID 68539	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Electrical Inspection / Jurtin Vide: 223 s Marion - rough electric /Permit 9156. ID 67882	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 950 N Supreme - final sign 9266, 68609	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 950 N SUPREME -SIGN 9266, 68394	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 951 W THORNDALE SIGN - 9267, 68395	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 951 W THORNDALE - SIGN 9267, 68610	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 S COUNTY LINE RD - WALL PRE POUR 8855, 70618	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Building/Structural Inspection / David DeLeon: 865 S BRENTWOOD - FIREPLACE 8899, 70626	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 860 N THOMAS FINAL - 9406, 69551	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 860 N THOMAS - FINAL 9406, 69549	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 8

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Plumbing Inspection / Dan Witkowski: 149 E George - 9215, 68011	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/23/2019 - SFR Plumbing Inspection / Dan Witkowski: 400 N Spruce - rough 9289, 68541	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/24/2019 - SFR Building/Structural Inspection / Jurtin Vide: 123 Jacquelyn- final patio /Permit 9477. ID 70095	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/24/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1050 s county line rd- trench wall pre pour /Permit 8855. ID 70688	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/24/2019 - SFR Building/Structural Inspection / Jurtin Vide: 317 e Washington- post holes fence /Permit 9447. ID 69871	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 930-950 w Irving park- slab on grade /Permit 9505. ID 70359	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 930 w Irving park- final pavement /Permit 9364. ID 69423	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce ave- NEW SFR insulation firestop /Permit 9289. ID 68857	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - SFR Building/Structural Inspection / Jurtin Vide: 400 n spruce- NEW SFR foundation insulation /Permit 9289. ID 68543	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 430 n Meyer- final building /Permit 9455. ID 69925	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1010 w foster- slab on grade pre pour /Permit 9292. ID 70720	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1050 s county line rd- trench wall and piers pre pour /Permit 8855. ID 70719	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - SFR Building/Structural Inspection / Jurtin Vide: 501 e red oak- NEW SFR footing pre pour /Permit 8975. ID 66183	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 9

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 13 w main st- slab on grade /Permit 9504. ID 70483	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 860 n Thomas- rough electric /Permit 9213. ID 67988	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 860 n Thomas- final electric /Permit 9213. ID 67992	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski: 620 S York Rd - in house plan review	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski: 659 W Supreme - in house plan review	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski: 699 Supreme - in house plan review	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/25/2019 - SFR Plumbing Inspection / Dan Witkowski: 149 E George - 9215, 70662	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/26/2019 - SFR Building/Structural Inspection / David DeLeon: 149 E GEORGE - INSULATION 9215, 68386	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/26/2019 - SFR Electrical Inspection / David DeLeon: 865 BRENTWOOD ROUGH - 8899, 70546	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/26/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski: 1208 W Irving Park Rd - rough 9120, 67331	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/26/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski: 350 N York - Underground 9473, 70467	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 736 Birginal - final 9466, 70164	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 County Line Rd - foundation 8855, 70799	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - SFR Building/Structural Inspection / David DeLeon: 501 E Red Oak - pre pour 8975, 70749	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - SFR Building/Structural Inspection / David DeLeon: 865 Brentwood - fireplace 8899, 70663	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0060632-IN

Invoice Date: 09/30/19

Page: 10

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - SFR Building/Structural Inspection / David DeLeon: 327 W Grove - post holes 9492, 70240	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - SFR Plumbing Inspection / Dan Wilkowski: 865 Brentwood - rough 8899, 65318	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/27/2019 - SFR Plumbing Inspection / Dan Wilkowski: 865 Brentwood - gas piping 8899, 65314	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/30/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1208 w Irving park- rough framing /Permit 9120. ID 67332	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 09/30/2019 - SFR Building/Structural Inspection / Jurtin Vide: 865 s Brentwood ct- rough framing /Permit 8899. ID 65320	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 09/30/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1208 w Irving park- rough electric /Permit 9120. ID 67330	1.00	43.75	43.75

Amount Due

5,022.50


09302019BENSNVL-1

Remit Payment to:
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	5,022.50
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	<u>5,022.50</u>



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538



Invoice ID **09302019BENSNVL-2**
Issue Date **10/01/2019**
Due Date **10/31/2019 (Net 30)**
Subject **VILLAGE OF BENSENVILLE PLAN REVIEW
SERVICES - SEPTEMBER 2019**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Plan Review	4250-CECHI-IL-PR - 09/12/2019 - MFR/Commercial Addition 0 to 2500 sf (building +3 disciplines) / Gerald Keys: 350 N York Rd - Non Residential Alterations - PERMIT 9473 - 1st review - Approved with notes	1.00	\$755.00	\$755.00
Plan Review	4250-CECHI-IL-PR - 09/25/2019 - SFR Addition >500sf / Gerald Keys: 225 E Pine Ave - Residential addition - PERMIT 9546 - 1st review - Approved with notes	1.00	\$420.00	\$420.00

Amount Due **\$1,175.00** OK
DL



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **09302019BENSNVL-1**
Issue Date **09/01/2019**
Due Date **10/01/2019 (Net 30)**
Subject **VILLAGE OF BENSENVILLE PLAN REVIEW
SERVICES - SEPTEMBER 2019**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Plan Review	4250-CECHI-IL-PR - 09/12/2019 - MFR/Commercial Addition 0 to 2500 sf (building +3 disciplines) / Gerald Keys: 350 N York Rd - Non Residential Alterations - PERMIT 9473 - 1st review - Approved with notes	1.00	\$755.00	\$755.00

Amount Due \$755.00



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **09302019BENSNVL-2**
Issue Date **10/01/2019**
Due Date **10/31/2019 (Net 30)**
Subject **VILLAGE OF BENSENVILLE PLAN REVIEW
SERVICES - SEPTEMBER 2019**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Plan Review	4250-CECHI-IL-PR - 09/25/2019 - SFR Addition >500sf / Gerald Keys: 225 E Pine Ave - Residential addition - PERMIT 9546 - 1st review - Approved with notes	1.00	\$420.00	\$420.00

Amount Due \$420.00



From

SAFEbuilt IL

SAFEbuilt

Attn: Mike Garcia

3755 Precision Drive, Suite 140

Loveland, CO 80538

Invoice ID **10312019BENS NVL-1**

Issue Date 11/01/2019

Due Date 12/01/2019 (Net 30)

Subject VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - OCTOBER 2019

Invoice For

06-BENS NVL

Village of Bensenville

Community & Economic Development

12 South Center Street

Bensenville, IL 60106



Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 10/01/2019 - SFR Building/Structural Inspection / Jurtin Vide: 224 s York rd- slab on grade Permit 9169. ID 70358	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/01/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1004 w Irving park- rough framing Permit 9426. ID 69706	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/01/2019 - SFR Building/Structural Inspection / Jurtin Vide: 865 s Brentwood ct- final chimney Permit 8899. ID 70816	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/01/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 745 n Birginal B- rough framing Permit 8608. ID 62886	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/01/2019 - SFR Building/Structural Inspection / Jurtin Vide: 321 w wood st- concrete piers Permit 9552. ID 70837	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/01/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1050 s county line- trench wall pre pour Permit 8855. ID 70865	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/01/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 745 n Birginal B- rough electric Permit 8608. ID 62884	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/01/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1225 E Devon- underground electric Permit 9428. ID 70866	1.00	\$43.75	\$43.75

REQUISITION # 20194495 - 11/26/19

Inspections	4000-CECHI-IL-BI - 10/02/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1208 w Irving park- Insulation Permit 9120. ID 68808	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/02/2019 - SFR Building/Structural Inspection / David DeLeon: 317 E Washington - final 9447, 69960	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/02/2019 - SFR Building/Structural Inspection / David DeLeon: 501 Red Oak - pre pour 8975, 66184	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/02/2019 - SFR Building/Structural Inspection / David DeLeon: 224 S York Rd - slab 9169 70893	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/02/2019 - SFR Building/Structural Inspection / David DeLeon: 501 Red Oak - pre pour 8975, 70925	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/02/2019 - MFR/Commercial Mechanical Inspection / Jurtin Vide: 1208 w Irving- drop ceiling partial Permit 9120. ID 67328	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/02/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1208 w Irving- drop ceiling partial Permit 9120. ID 67329	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/03/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1208 W IRVING PARK - 9120, 70937	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 350 N YORK RD - 9473, 70466	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/04/2019 - SFR Building/Structural Inspection / David DeLeon: 530 E RED OAK - FINAL 9439, 69961	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1301 W IRVING PARK RD - FINAL 9441, 69809	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/04/2019 - SFR Building/Structural Inspection / David DeLeon: 501 E RED OAK - FINAL 8975, 70969	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1225 W DEVON - FINAL 9428, 69720	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 10/04/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1225 W DEVON - SLAB ON GRADE 9428,69830	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/04/2019 - SFR Building/Structural Inspection / David DeLeon: 501 E RED OAK - INSULATION 8975, 66205	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/04/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 383 EVERGREEN - FINAL 9312, 68715	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/04/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1225 W DEVON - FINAL 9428, 69719	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Mechanical Inspection / Jurtin Vide: 1057 s York- final Permit 9136. ID 67451	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1057 s York- final Permit 9136. ID 67452	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1050 s York- trench wall pre pour Permit 8855. ID 70985	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1090 thorn dale- rough framing Permit 9519. ID 70584	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - SFR Building/Structural Inspection / Jurtin Vide: 152 e Jacquelyn- slab on grade pre pour Permit 9509. ID 70700	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 951 n thorn dale - final Permit 9166. ID 67661	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1057 s York- final Permit 9136. ID 67450	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/07/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1090 thorn dale - rough Permit 9519. ID 70470	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 10/08/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 490 supreme- basin repair & surround pre pour Permit 9560. ID 70898	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/08/2019 - SFR Building/Structural Inspection/ David DeLeon: 1009 BROOKWOOD - PRE POUR 8629, 63608	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/08/2019 -SFR Building/Structural Inspection / David DeLeon: 244 N MARSHALL - POST HOLES 9274, 68419	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 1057 S York Rd. Permit 9136 # 67829 Final Plumbing Approved	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 14 N York Rd. Permit 9006 # 66439 Office Only final plumbing. Approved	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 1050 S. Country Line Rd. Permit 8877 # 65088 Underground gas piping Approved	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/09/2019 - SFR Building/Structural Inspection/ Vince Cirone: 1308 W. Brookwood Permit 9322 # 68770 Final for Concrete	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Building/Structural Inspection / Vince Cirone: 13 W. Main Permit 9504 # 70356 Final for concrete pad for dumpster.	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Building/Structural Inspection / Vince Cirone: 930 W. Irving Park Rd. Permit 9505 # 70366 Final concrete	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 951 n thornedale- piers pre pour Permit 9407. ID 69939	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/09/2019 - SFR Building/Structural Inspection/ Jurtin Vide: 217 s center - slab on grade pre pour Permit 9469. ID 70183	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/09/2019 - SFR Building/Structural Inspection / Jurtin Vide: 177 Henderson- piers pre pour Permit 9130. ID 67393	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 10/09/2019 - SFR Building/Structural Inspection / Jurtin Vide: 865 s Brentwood ct- NEW SFR Insulation Permit 8899. ID 65321	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/09/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 1050 s county line- underground partial Permit 8855. ID 65080	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Plumbing Inspection / Ray Witkowski: 850 n York Rough plumbing 9473 ID 70065	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Building/Structural Inspection / Ray Witkowski: 850 n York Rough structural 9473 ID 70066	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Electrical Inspection / Ray Witkowski: 850 n York Rough electrical 9473 ID 70064	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - SFR Building/Structural Inspection / Ray Witkowski: 850 n York Insulation 9473 ID 60468 70468 	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Plumbing Inspection / Ray Witkowski: 1091 entry dr. Plan review	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 854 GOLF - FINAL 9508, 70393	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - SFR Building/Structural Inspection / David DeLeon: 321 WOOD - PIERS 9552, 70892	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/10/2019 - SFR Building/Structural Inspection / David DeLeon: 235 SPRUCE - SLAB 9554, 71002	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 104 IRVING PARK RD - SLAB 8592, 70748	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 877 N SUPREME - FINAL 9391, 69438	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 18 E GREEN - FINAL 9311, 69077	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/10/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 877 N SUPREME - FINAL 9391, 70017	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/11/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 County Line Rd - 8877, 65561	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/11/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1047 S YORK - FINAL 9373, 69288	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/11/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1047 S YORK - FINAL 9373, 69499	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/14/2019 - MFR/Commercial Plumbing Inspection / Ray Witkowski: 300 beeline dr Rough underground Id: 70257	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/14/2019 - SFR Building/Structural Inspection / Jurtin Vide: 263 s Judson- final fence Permit 9087. ID 67153	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/14/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 854 w golf ln- final racking Permit 9508. ID 71132	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/14/2019 - MFR/Commercial Mechanical Inspection / Jurtin Vide: 146 w Irving park- drop ceiling Permit 9379. ID 69327	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/14/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 146 w Irving park- electric service Permit 9379. ID 71198	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/14/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 146 w Irving park- drop ceiling Permit 9379. ID 69328	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/15/2019 - MFR/Commercial Mechanical Inspection / Jim Kemper: 361 N. MARSHALL RD. PERMIT 8814 INSPECTION ID 65904 ROUGH MECHANICAL	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 10/15/2019 - MFR/Commercial Plumbing Inspection / Jim Kemper: 361 N. MARSHALL RD. PERMIT 8814 INSPECTION ID 64406 ROUGH PLUMBING	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/15/2019 - SFR Plumbing Inspection / Jim Kemper: PLAN REVIEW 16 E. PINE AVE. PERMIT 9602 PLAN REVIEW ID 71177	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/15/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 400 w frontier way- final fire alarm Permit 9451. ID 69895	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/15/2019 - SFR Building/Structural Inspection / David DeLeon: 320 W Grove - piers 9566, 70962	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/15/2019 - SFR Building/Structural Inspection / David DeLeon: 321 W Wood - rough 9552, 70838	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/15/2019 - SFR Building/Structural Inspection / David DeLeon: 321 Wood - final 9552, 70839	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/15/2019 - SFR Building/Structural Inspection / David DeLeon: 137 George - final 9187, 67965	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/15/2019 - SFR Building/Structural Inspection / David DeLeon: 1545 Indian Hill - piers 9435, 70237	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/15/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1208 W Irving Park - 9120, 68804	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 114 e pine Ave- piers pre pour fence Permit 9530. ID 70549	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/16/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 951 w thorndale- final sign Permit 9407. ID 69556	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/16/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 1050 s county line- slab on grade pre pour Permit 8877. ID 71223	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/16/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 975 w Bryn mawr- final racking Permit 9563. ID 70835	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 10/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 268 s center- garage floor pre pour Permit 8781. ID 64124	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 320 w grove ave- final fence Permit 9566. ID 70963	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/16/2019 - SFR Building/Structural Inspection / Jurtin Vide: 1018 brookwood st- electric service Permit 9526. ID 70929	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1004 Irving Park - pre pour 9553, 70882	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Building/Structural Inspection / David DeLeon: 1020 Glendale - final 9445, 69857	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Building/Structural Inspection / David DeLeon: 172 S Foley - final 9304, 68666	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Building/Structural Inspection / David DeLeon: 248 S York - pre pour stairs 9580, 71077	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Building/Structural Inspection / David DeLeon: 248 S York - sidewalk 9580, 71080	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Building/Structural Inspection / David DeLeon: 321 W Wood - piers 9552, 72290	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Plumbing Inspeccion / Dan Witkowski: 1020 Glendale permit 9445 insp Id. 70935 plumbing inspection Rough	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/18/2019 - SFR Plumbing Inspeccion / Dan Witkowski: 1020 Glendale permit3 9445 inspection Id 70936 plumbing inspection water heater	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/21/2019 - SFR Building/Structural Inspection / David DeLeon: 676 Redmond - slab 9603, 71190	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/21/2019 - SFR Building/Structural Inspection / David DeLeon: 321 Wood - final 9552, 71219	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/21/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 24 S Addison - final 8902, 65381	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/21/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 18 E Green - final 9311, 71133	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 10/22/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 459 W Industrial - foundation 9458, 70045	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/22/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1050 County Line Rd - slab 8877, 72309	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/22/2019 - SFR Building/Structural Inspection / David DeLeon: 244 S Center - slab 9589, 71101	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/23/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 759 w industrial- pre pour foundation wall Permit 9458. ID 72400	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/23/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 11 w gateway- final sign Permit 9031. ID 6660 <i>66660 DL</i>	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/23/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 11 w gateway- final building Permit 9190. ID 67791	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/23/2019 - SFR Building/Structural Inspection / Jurtin Vide: 114 e pine- final fence Permit 9530 ID 70763	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/23/2019 - SFR Electrical Inspection / Jurtin Vide: 1241 n ash ave- underground electric Permit 9454. ID 70532	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/23/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 11 w gateway- final sign Permit 9031 ID 66722	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/23/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 11 w gateway- final electric Permit 9190. ID 67790	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/23/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 759 W Industrial - Pre Pour 9458, 72355	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/24/2019 - SFR Plumbing Inspeccion / Dan Witkowski: 347 Diana Ct permit# 9533 inspection Id 70890 Rough	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/24/2019 - SFR Building/Structural Inspection / David DeLeon: 1545 Indian Hill - final 9435, 69776	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 10/24/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 1143 S York - framing 9533, 70906	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/24/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1143 S York - rough 9533, 70904	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/24/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 11 Gateway - 9031, 72401	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/24/2019 - SFR Building/Structural Inspection / David DeLeon: 1339 Indian Hill - Electrical Service 9599, 72263	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/24/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 11 GATEWAY - FINAL 9190, 72403	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/25/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone: 300 W. Beeline Dr. Permit 9456 # 69930 Final plumbing trench drain.	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/25/2019 - SFR Electrical Inspection / Vince Cirone: 401 E. Jefferson Permit 9348 # 69158 Final Electric.	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/25/2019 - SFR Plumbing Inspection / Vince Cirone: 401 E. Jefferson Permit 9348 # 69161 Final kitchen Plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/25/2019 - SFR Building/Structural Inspection / David DeLeon: 446 Judson - final 9015, 66590	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/25/2019 - SFR Building/Structural Inspection / David DeLeon: 120 N Center - damproofing 9622, 72249	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/25/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 200 William St - 9513, 70425	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/25/2019 - SFR Building/Structural Inspection / David DeLeon: 223 S Marion - Insulation 9156, 67883	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/25/2019 - SFR Building/Structural Inspection / Vince Cirone: 401 E Jefferson - final 9348, 68992	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/28/2019 - SFR Building/Structural Inspection / David DeLeon: 1045 S CENTER - PIERS 9117, 67321	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/28/2019 - SFR Building/Structural Inspection / David DeLeon: 210 S MINER - FINAL 9242, 68226	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 10/28/2019 - MFR/Commercial Electrical Inspection / David DeLeon: 1250 N ELLIS - FINAL 9503, 70342	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/29/2019 - SFR Building/Structural Inspection / David DeLeon: 1013 Medinah - final 9382, 69443	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/29/2019 - SFR Electrical Inspection / David DeLeon: 1013 Medinah - final 9382, 69553	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/29/2019 - SFR Building/Structural Inspection / David DeLeon: 120 N CENTER ST - FINAL 9622, 71218	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/29/2019 - SFR Building/Structural Inspection / David DeLeon: 202 E JACQUELYN - ROUGH 9573, 70923	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/29/2019 - SFR Building/Structural Inspection / David DeLeon: 202 E JACQUELYN - FINAL 9573, 70924	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/29/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon: 390 HILLSIDE - PRE POUR 9404, 69688	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/30/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 601 IL RTE 83- concrete piers pre pou Permit 8817. ID 65335	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/30/2019 - SFR Mechanical Inspection / David DeLeon: 149 E GEORGE - FINAL 9215, 68015	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/30/2019 - SFR Building/Structural Inspection / David DeLeon: 149 E GEORGE - FINAL 9215, 68016	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/30/2019 - SFR Electrical Inspection / David DeLeon: 149 E GEORGE - FINAL 9215, 68014	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/30/2019 - SFR Electrical Inspection / David DeLeon: 149 E GEORGE - SERVICE 9215, 68399	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/30/2019 - SFR Plumbing Inspection / Dan Witkowski: 149 E.George permit# 9215 insp ID # 68383 gas piping	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 10/30/2019 - SFR Plumbing Inspection / Dan Witkowski: 149 E.George permit# 9215 insp ID # 68013 final Plumbing	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 10/30/2019 - MFR/Commercial Mechanical Inspection / Jurtin Vide: 350 n York- drop ceiling Permit 9473. ID 70062	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/30/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide: 330 s county line-final sign Permit 9268. ID 68400	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 10/30/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide: 350 n York- drop ceiling Permit 9473. ID 70063	1.00	\$43.75	\$43.75

Amount Due

\$5,643.75

OK
Vol.



- Inspection INVOICE only
- No plan REVIEWS were done

From


SAFEbuilt IL

SAFEbuilt

Attn: Mike Garcia

3755 Precision Drive, Suite 140

Loveland, CO 80538



Invoice ID 11302019BENS NVL-1
Issue Date 12/01/2019
Due Date 12/31/2019 (Net 30)
Subject VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - NOVEMBER 2019

Invoice For

06-BENS NVL

Village of Bensenville

Community & Economic Development

12 South Center Street

Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 11/01/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 251 Center - slab 9520, 70767	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/01/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 223 Marion - final 9156, 67586	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/01/2019 - SFR Electrical Inspection / David DeLeon 000203: 223 Marion final , 9156, 67884	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/04/2019 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 350 York rd Final plumbing Id: 70067	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/04/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 350 n York- final building Permit 9473 ID 70070	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/04/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 747 s Dennis- final fence Permit 9152. ID 67679	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/04/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 268 s center- rough framing/garage Permit 8781 ID 64126	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/04/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 234 n walnut- draintile & dampproofing Permit 9623. ID 72328	1.00	\$35.00	\$35.00

REQUISITION # 20194599
12.6.19

Inspections	4000-CECHI-IL-BI - 11/04/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 350 n York- final Permit 9473. ID 70068	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/05/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 251 s center- pavement final Permit 9520. ID 70768	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/05/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 745 plentywood- post holes fence Permit 9288. ID 68513	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/05/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 350 n York- final fire alarm Permit 9647. ID 72633	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/06/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 820 river forest- pre pour service walk/driveway Permit 9656. ID 72519	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/06/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 235 spruce- final driveway/service walk Permit 9554. ID 71003	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/07/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 111 E PINE - POST HOLES 9434, 69766	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/07/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 244 S CENTER - FINAL 9589, 71102	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/07/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1050 S COUNTY LINE RD - UG ELECTRICAL 8877, 72696	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/07/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 601 RTE 83 - UG 8817, 65334	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/08/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 1209 W MEDINAH - FRAMING 9446, 69864	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/08/2019 - SFR Electrical Inspection / David DeLeon 000203: 1209 W MEDINAH - ROUGH 9446, 70021	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 11/08/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 361 N MARSHALL - ROUGH 8814, 72711	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/08/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 361 N MARSHALL - ROUGH 8814, 70382	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/08/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1050 S COUNTY LINE RD - 8817, 72504	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/08/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 601 N RTE 83 - SLAB 8817, 65333	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/12/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 222 e pine- final Permit 9172. ID 67698	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/12/2019 - SFR Electrical Inspection / Jurtin Vide 002013: 222 e pine- final Permit 9172. ID 67840	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/12/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 222 E PINE PERMIT# 9172 INSPECTION ID # 67839 FINAL PLUMBING	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/12/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 16 E PINE PERMIT# 9602 INSP ID # 71235 SEWER INSP. PARTIAL	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/12/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 16 E PINE AVE PERMIT # 9602 INSP. ID # 71236 ROUGH	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/13/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1091 s entry dr- slab on grade Permit 9600. ID 72239	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/13/2019 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 1091 S.ENTRY DR PERMIT# 9600 INSP ID # 72237	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/13/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 16 E PINE AVE PERMIT# 9602 INSP ID #72774	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 11/14/2019 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 1091 ENTRY DR PERMIT # 9600 INSP.ID# 72238 FINAL PLUMBING INSP	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/14/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 222 SIEVERT - FINAL 9260, 68350	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/14/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 222 SIEVERT - SLAB 9260, 68603	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/14/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 222 SIEVERT - FINAL 9260, 68604	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/14/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 699 SUPREME - FIRE ALARM 9612, 71167	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/18/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 16 E.PINE PERMIT# 9602 INSP ID# 72773 ROUGH PLUMBING	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/18/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 16 E.PINE PERMIT# 9602 INSP. ID # 71237 final plumbing insp	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/19/2019 - SFR Plumbing Inspeccion / Jim Kemper 000266: 615 W. GREEN ST. PERMIT 8900 INSPECTION 66796 ROUGH PLUMBING	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/19/2019 - MFR/Commercial Building/Structural Inspection / Jim Kemper 000266: 1050 COUNTY LINE RD. PERMIT 8877 ID 65560 INSPECTION SLAB ON GRADE	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/19/2019 - SFR Plumbing Inspeccion / Jim Kemper 000266: 347 E. DIANA CT. PERMIT 9533 INSPECTION 70889 FINAL PLUMBING	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/20/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 303 s Hawthorne- final Permit 9111. ID 67289	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 11/20/2019 - SFR Electrical Inspection / Jurtin Vide 002013: 303 s Hawthorne- final Permit 9111. ID 69914	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/20/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1215 w Irving park- final sign Permit 9257. ID 68322	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/20/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1215 w Irving park- final sign Permit 9257. ID 69846	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/21/2019 - MFR/Commercial Electrical Inspection / Ray Witkowski 002124: 745 birginal Final electrical fire alarm 67140	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/22/2019 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 745 N birginal permit# 9115 insp id# 67308 final roof -flat	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/22/2019 - SFR Building/Structural Inspection / Dan Witkowski 002544: 252 S.Addison st permit# 9699 insp id # 72935 slab on grade insp	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/22/2019 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 15 grand permit# 9709 ID# 72927 plan review	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/22/2019 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 659-699 suprne dr permit# 9704 ID# 72926 plan review	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/22/2019 - SFR Electrical Inspection / David DeLeon 000203: 242 PINE LN - ROUGH 9668, 72664	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/25/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 615 W Green P# 8900 ID# 66793 slab on grade	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/25/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 615 green P# 8900 ID# 66794 drain tile and dumprofig	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/25/2019 - SFR Mechanical Inspection / Dan Witkowski 002544: 420 S.Addison P# 9443 ID# 69999 final mechanical hvac	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 11/25/2019 - SFR Building/Structural Inspection / Dan Witkowski 002544: 420 S.Addison P# 9321 ID# 68760 final roof	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/25/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 622 W MCClean P# 9697 ID# 72769 water heater	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/25/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 474 N THOMAS FINAL - 9633, 72319	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/25/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 975 W BRYN MAWR - FRAMING 9674, 72615	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/25/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1004 W IRVING PARK RD - SLAB 9426, 70108	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/25/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1004 W IRVING PARK ROAD - ROUGH 9426, 69704	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/25/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 14 N YORK RD - FINAL 9468, 72445	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/25/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 14 N YORK RD - 9468, 70033	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/26/2019 - MFR/Commercial Plumbing Inspection / Jim Kemper 000266: 1004 W. IRVING PARK RD. PERMIT 9426 INSPECTION 69705 ROUGH PLUMBING	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Plumbing Inspeccion / Jim Kemper 000266: 142 S. WALNUT PERMIT 9332 INSPECTION 69085 FINAL PLUMBING	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 142 S WALNUT - FINAL 9332, 68871	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Electrical Inspection / David DeLeon 000203: 142 S WALNUT - FINAL 9332, 69084	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Mechanical Inspection / David DeLeon 000203: 1209 W ELMHURST - FINAL 9696, 72778	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 252 S ADDISON - 9269, 68598	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 252 S ADDISON - 9269, 68405	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/26/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 252 S ADDISON - FINAL 9699, 72936	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/26/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1004 W IRVING PARK RD - SLAB 9426, 72973	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/26/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1004 W IRVING PARK RD - CEILING 9426, 69703	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/27/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1004 W Irving park dr P# 9426 ID# 69707 final Plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/27/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 232 s center- final building Permit 9649. ID 72473	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/27/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1004 w Irving park- final Permit 9426. ID.69710	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 11/27/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 242 n pine ln- insulation Permit 9668. ID 72964	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 11/27/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1004 w Irving park- final Permit 9426. ID 69708	1.00	\$43.75	\$43.75

Amount Due **\$3,045.00**

OK
DL

Invoice



Invoice Number: 0065211-IN

Invoice Date: 12/31/19

Terms: Net 30 Days

Due Date: 01/30/20

Salesperson: SNO

Customer Number: 06-BENSNVL

Customer P.O.:

12312019BENSNVL-1

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 12/02/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 1033 w wood st- concrete piers pre pour /Permit 9610. ID 71208	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/02/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1143 s York- final /Permit 9570. ID 70909	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/02/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1143 York rd- final /Permit 9570 ID 70908	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/02/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 745 n Birginal- final /Permit 8608. ID 62888	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/02/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 1033 w wood st- concrete piers /Permit 9610. ID 73081	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/03/2019 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 430 n country club dr /Plan review /73077	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/03/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 14 N. York rd- final siding /Permit 9358. ID 69099	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/03/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 902 IL RTE 83- underground /Permit 9393. ID 69656	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/04/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 344 s park st- underground generator /Permit 9463. ID 70855	1.00	43.75	43.75

Continued

1.8.2020
Requisition # 20194905



Village of Bensenville

Invoice Number: 0065211-IN

Invoice Date: 12/31/19

Page: 2

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 12/04/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 343 s park st- final generator /Permit 9463. ID 70856	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/05/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 142 s walnut st- final building /Permit 9332. ID 73040	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/05/2019 - SFR Electrical Inspection / Jurtin Vide 002013: 142 s walnut st- final electric /Permit 9332. ID 73039	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/05/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 106 W Foster /Permit 9725 /Id 73071 /Water heater	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/05/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 430 Country Club /Permit 9724 /Id 73128 /Underground rough	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/09/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 975 W.Bryn Mawr Permit# 9674 ID# 72690 /rough inspection	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/10/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 975 BRYN MAWR - SLAB 9674, 73171	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/10/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 248 S YORK RD - FINAL 9580, 71079	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/10/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 902 RTE 83 - SLAB ON GRADE 9393, 69655	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/10/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 474 n Thomas- slab on grade /Permit 9632 ID 72344	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/12/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 975 w Bryan mawr- slab on grade /Permit 9674. ID 72693	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/12/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 460 W Irving Park /id # 73212 Permit # 9735 /Plan review	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065211-IN

Invoice Date: 12/31/19

Page: 3

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 12/12/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1208 W IRVING PARK RD - FINAL 9120, 67336	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/12/2019 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 1208 W IRVING PARK RD - 9120, 67335	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/12/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1208 W IRVING PARK RD - 9120, 67334	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/13/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1208 W.Irving Park /Id # 67333 Permit# 9120 /final Plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/13/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 330 MEMORIAL - FINAL 9197, 67873	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/13/2019 - SFR Electrical Inspection / David DeLeon 000203: 330 MEMORIAL - FINAL 9197, 68118 #68108 DL	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/13/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 244 MARSHALL - FINAL 9274, 68781	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/16/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 659 SUPREME - 9596, 71063	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/16/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 192 S MAY - DEMO 9706, 72945	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/16/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 268 CENTER - FINAL 8781, 64127	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1143 s. York-final sign /Permit 9585. ID 71001	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 15 W.Grand ave /Permit # /ID # 73266 /plan review	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 100 E.George st /ID#73267 /plan review	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065211-IN

Invoice Date: 12/31/19

Page: 4

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1208 w Irving park- final /Permit 9120. ID 73229	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 1208 w Irving park- final /Permit 9120. ID 73230	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 361 Marshall- insulation /Permit 8814. ID 65882	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1208 w Irving park- final /Permit 9120. ID 73231	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1143 s York- final sign /Permit 9585. ID 71086	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/17/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 400 n country club- final solar panels /Permit 9231. ID 68130	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/18/2019 - SFR Building/Structural Inspection / Jurtin Vide 002013: 400 spruce- NEW SFR final /Permit 9289. ID 68550	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/18/2019 - SFR Electrical Inspection / Jurtin Vide 002013: 400 spruce- NEW SFR final /Permit 9289. ID 68548	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/18/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 790 w maple- slab on grade /Permit 9658. ID 73022	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/18/2019 - SFR Mechanical Inspection / Jurtin Vide 002013: 400 spruce- NEW SFR final /Permit 9289. ID -73322	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/18/2019 - SFR Plumbing Inspection / Dan Witkowski 002544: 400 Spruce ave /permit# 9289 ID # 68547 /final plumbing insp	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/19/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 601 n IL RTE 83- final building /Permit 8817. ID 64449	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065211-IN

Invoice Date: 12/31/19

Page: 5

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 12/19/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 790 w maple- foundation wall pre pour /Permit 9658. ID 73023	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/19/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 601 IL RTE 83- final /Permit 8817. ID 64447	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/19/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 125 w grand- underground /Permit 9691. ID 72940	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/19/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 125 w grand- pre pour /Permit 9691. ID - 72995 ⁷²⁹³⁸ 	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/19/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 659 W.Supreme /permit # 9704 ID # 72963 /Final Plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/20/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 125 W Grand - piers 9691, 73335	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/20/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 125 W Grand - UG 9691, 73336	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/20/2019 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 241 S Park - final 9521, 70777	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/20/2019 - MFR/Commercial Plumbing Inspection / Vince Cirone 002379: Rough Plumbing Approved. Permit 9724 # 73063	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/23/2019 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 560 w supreme- foundation wall pre pour /Permit 9700. ID 72972	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/23/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: Permit 8824 /Id 70600 /411 Dominic ct /Underground plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/26/2019 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: Permit 9674 /Id 72616 /975 Bryn Mawr /Final plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/27/2019 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1055 County Line - service 8877, 65085	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065211-IN

Invoice Date: 12/31/19

Page: 6

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 12/27/2019 - SFR Building/Structural Inspection / David DeLeon 000203: 1103 Brookwood - final 9366, 69305	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 12/30/2019 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 460 s evergreen- final fire alarm /Permit 9646. ID 72457	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 12/30/2019 - SFR Plumbing Inspeccion / Dan Witkowski 002544: Permit 9755 /lag™d. 73423 /347 Diana ct /Water heater final	1.00	35.00	35.00

Amount Due

2,572.50

12312019BENSNVL-1

Remit Payment to:
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	2,572.50
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	2,572.50

Invoice



Invoice Number: 0065772-IN

Invoice Date: 01/31/20

Terms: Net 30 Days

Due Date: 03/30/20

Salesperson: SN0

Customer Number: 06-BENSNVL

Customer P.O.:

01312020BENSNVL-1

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Item Type	Description	Qty	Unit Price	Amount
PLAN REVIEW	4250-CECHIL-PR - 01/28/2020 - MFR/Commercial Addition 10,001 sf (building + 3 disciplines) / Gerald Keys 001730: 114 W Green St - Multifamily commercial mixed building - PERMIT 9785 - 1st review -	1.00	1,950.00	1,950.00
PLAN REVIEW	4250-CECHIL-PR - 01/28/2020 - Each 1000sf over 10,000 - building + 3 disciplines / Gerald Keys 001730: 114 W Green - 10,888 sf.	1.00	40.00	40.00
Amount Due				1,990.00

OK
CL

01312020BENSNVL-1

Remit Payment to:
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice: 1,990.00
Freight: 0.00
Sales Tax: 0.00
Invoice Total: 1,990.00

OK
CL

REQUISITION # 20200512
2-10-20

Invoice



Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Terms: Net 30 Days

Due Date: 03/30/20

Salesperson: SN0

Customer Number: 06-BENSNVL

Customer P.O.:

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

01312020BENSNVL-2

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECH-IL-BI - 01/02/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 610 supreme dr- rough framing /Permit 9662. ID 72550	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/02/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 615 w green st- rough framing /Permit 8900. ID 65346	1.00	35.00	35.00
INSPECTIONS	4000-CECH-IL-BI - 01/03/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 240 FOSTER - 9637, 73199	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/03/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 474 N THOMAS - PRE POUR 9631, 72345	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/03/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 474 THOMAS - FINAL 9631, 72297	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/03/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 430 COUNTRY CLUB - ROUGH 9724, 73062	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/06/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 644 s York rd- final building /Permit 9536. ID 60637	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/06/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 474 Thomas dr- final building /Permit 9631. ID 72298	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/06/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: Permit 9549 ID 70707 /1033 Bryn Mavr /Rpz and backflow inspection	1.00	43.75	43.75
INSPECTIONS	4000-CECH-IL-BI - 01/06/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: Permit 9735. ID 73190 /Rough plumbing inspection	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Page: 2

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 420 w green- post hole fence /Permit 9429. ID 69742	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 146 w Irving- final building /Permit 9379. ID 69335	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 240 w foster- foundation wall pre pour /Permit 9637. ID 73200	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 902 RTE 83- slab on grade /Permit 9393. ID 73591	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 430 n country club- slab on grade /Permit 9724 ID 73593	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1204 w Irving park- final sign /Permit 9108 ID 67275	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 146 w Irving park- final /Permit 9379. ID 69333	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1204 w Irving park- final /Permit 9108. ID 68776	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: Permit. 9379. Is. 72430 69332 /146 w Irving park rd /Rough plumbing Final	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/07/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: Permit. 9724. Is. 72430 73130 /430 Country Club /Rough plumbing Gas Piping	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 1104 w hillside- final building /Permit 9298. ID 68638	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 117 w main st - final fire alarm /Permit 9701. ID 73030	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Page: 3

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1050 s county line- rough /Permit 8877. ID 65091	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 205 s park- final fire alarm /Permit 9331. ID 69136	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 361 n Marshall- service /Permit 8814. ID 65876	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 920 w Irving park- final /Permit 9758. ID 73486	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 902 RTE 83- rough /Permit 9393. ID 69444	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 560 Supreme - final 9700, 72800	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 445 Center - final 9254 , 68366	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - SFR Building/Structural Inspection / Ray Witkowski 002124: 615 Green st /Rough structural #8900 /73648	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - MFR/Commercial Mechanical Inspection / Ray Witkowski 002124: 975 Bryn Mawr #9674 /Final hvac /72691	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - MFR/Commercial Building/Structural Inspection / Ray Witkowski 002124: 975 Bryn Mawr #9674 /Final /72618	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - MFR/Commercial Electrical Inspection / Ray Witkowski 002124: 975 Bryn Mawr #9674 /Final electrical 72617	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - MFR/Commercial Electrical Inspection / Ray Witkowski 002124: 975 Bryn Mawr #9674 /Drop ceiling electrical /72692	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Page: 4

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 01/10/2020 - SFR Building/Structural Inspection / Ray Witkowski 002124: 1045 s center st /Final hot tub slab and fence #9117 ID#67323	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/13/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1010 w Foster- final steel staircases /Permit 9292. ID 68577	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/13/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 501 Read Oak /Permit 8975 la€™d 66197 /Water service rough	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/13/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 501 Read Oak /Permit 8975 la€™d 66191 /Underground plumbing	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/14/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1140 s York- rough /Permit 9736. ID 73260	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/14/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1140 s York- final /Permit 9736. ID 73218	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1050 county line rd /Permit 8877 la€™d 65092 /Rough plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 620 S York /Permit 9550 la€™d 70712 /Plumbing final	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1050 s county line- rough framing /Permit 8877. ID 65094	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 460 w Irving park- rough framing /Permit 9735. ID 73191	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1090 thorn dale- final hotel model room /Permit 9519. ID 70475	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 460 w Irving park- rough electric /Permit 9735. ID 73189	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Page: 5

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1090 thorn dale- final hotel model room /Permit 9519. ID 70474	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/16/2020 - MFR/Commercial Plumbing Inspection / Jim Kemper 000266: 745 BIRGINAL AVE. /PERMIT 8608 /INSPECTION 62885 /ROUGH PLUMBING	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/17/2020 - MFR/Commercial Plumbing Inspection / Vince Cirone 002379: Permit 8824 # 64494 Rough plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/17/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 610 w supreme- final /Permit 9662. ID 72553	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/17/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 902 RTE 83- final fuel dispensers /Permit 9393. ID 69449	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/17/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 902 RTE 83- final fuel dispensers /Permit 9393. ID 69448	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/20/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 460 w Irving park- insulation/firestop /Permit 9735. ID 73805	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/20/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 560 w supreme- final fire alarm /Permit 9780. ID 73763	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/21/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 276 s center- final /Permit 7423. ID 54166	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/21/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 276 s center- final /Permit 7423. ID 54347	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/21/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 15 w grand /Permit 9709 ID 73275 /Rough plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/21/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 276 s center /Permit. 7423. ID 54348 /Final plumbing inspection	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Page: 6

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 01/23/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 125 w grand - pre pour concrete piers /Permit 9691. ID- 73902 73902	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/23/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 100 Devon- final masonry repairs /Permit 8703 ID 63563	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/23/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 117 read oak /Permit 9748 lae™d 73345 /Final plumbing	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/28/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 1050 county line - drop ceiling /Permit 8877. ID 65083	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 01/28/2020 - SFR Mechanical Inspection / Jurtin Vide 002013: 347 E Diana ct- final furnace /Permit 9764. ID 73604	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Plumbing Inspeccion / Vince Cirone 002379: 271 S. Addison St. Permit 9782 Plan review 73958 73958	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Plumbing Inspeccion / Vince Cirone 002379: Final Plumbing 242 Pine. Permit 9668 # 72663	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Plumbing Inspeccion / Vince Cirone 002379: 276 S. Center Permit 7423 # 73889 Final Kitchen	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Mechanical Inspection / David DeLeon 000203: 242 PINE LN - FINAL 9668, 72666	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 242 PINE LN - 9668, 72667	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Electrical Inspection / David DeLeon 000203: 242 PINE - FINAL 9668, 72665	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 1112 W TWIN OAKS - FINAL 9684, 72682	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/30/2020 - SFR Electrical Inspection / David DeLeon 000203: 1112 W TWIN OAKS - FINAL 9684, 72715	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 01/31/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 975 w Bryan mawr- final building /Permit 9674. ID 73735	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0065771-IN

Invoice Date: 01/31/20

Page: 7

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 01/31/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 601 w frontier- electric service /Permit 9749 ID 73377	1.00	43.75	43.75

Amount Due

3,010.00

01312020BENSNVL-2

Remit Payment to:
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice: 3,010.00
Freight: 0.00
Sales Tax: 0.00
Invoice Total: 3,010.00

Invoice

SAFEbuilt[✓]®

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Invoice Number: 0066391-IN

Invoice Date: 02/29/20

Terms: Net 30 Days

Due Date: 03/30/20

Salesperson: SN0

Customer Number: 06-BENSNVL

Customer P.O.:

02292020BENSNVL-1

Item Type	Description	Qty	Unit Price	Amount
PLAN REVIEW	4250-CECH-IL-PR - 02/19/2020 - MFR/Commercial Addition 5001 to 7500 sf (building + 3 disciplines) / Gerald Keys 001730: 640 S County Line Rd - Non res Bld - PERMIT 9813 - 1st review - Not Approved	1.00	1,400.00	1,400.00

Amount Due

1,400.00

Ok, DL

02292020BENSNVL-1

Remit Payment to: SAFEBuilt, LLC
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	1,400.00
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	1,400.00

REQUISITION # 20201331



From

SAFEbuilt IL

SAFEbuilt

Attn: Mike Garcia

3755 Precision Drive, Suite 140

Loveland, CO 80538

Invoice ID

~~02292020~~ BENS NVL-2

Issue Date

03/01/2020

Due Date

03/31/2020 (Net 30)

Subject

VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - FEBRUARY 2020

Invoice For

06-BENS NVL

Village of Bensenville

Community & Economic Development

12 South Center Street

Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 02/03/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 951 w thorn dale- slab on grade pre pour Permit 8955. ID 66229	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/03/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 951 w thorn dale- final slab on grade Permit 8955. ID 66025	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/03/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 601 w frontier way- slab on grade pre pour Permit 9759. ID 74002	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/04/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 631 IL RTE 83- drop ceiling Permit 9743. ID 73743	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/04/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1040 w industrial- final roof Permit 9319. ID 68753	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/04/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 631 IL RTE 83- drop ceiling Permit 9743. ID 73744	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/05/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1208 w Irving park- concrete piers sign Permit 9721. ID 73248	1.00	\$43.75	\$43.75

REQUISITION # 20201331

Inspections	4000-CECHI-IL-BI - 02/05/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 951 w thorn dale- final building Permit 9061. ID 68903	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/05/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 242 n line- final Permit 9668. ID 73978	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/05/2020 - SFR Mechanical Inspection / Jurtin Vide 002013: 242 n pine- final Permit 9668. ID 73977	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/05/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 242 n line- final Permit 9668. ID 73979	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/05/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 951 w thorn dale- final Permit 9061. ID 68902	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/05/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1208 w Irving park- underground sign Permit 9721. ID 73246	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/06/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 460 W IRVING PARK - CEILING 73187	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/06/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 460 W IRVING PARK - CEILING 9735, 73188	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/06/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 375 S EVERGREEN - FINAL 9722, 73053	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/07/2020 - MFR/Commercial Plumbing Inspection/ Walter Smith 002099: 213 n walnut st Plumbing inspection 8676, ID 66082	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/07/2020 - MFR/Commercial Plumbing Inspection/ Walter Smith 002099: 460 w Irving Park Plumbing Final Inspection 9735, ID 73192	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/07/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 460 W IRVING PARK RD - FINAL 73195	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 02/07/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 460 W IRVING PARK RD - FINAL 9735, 73193	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/11/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 921 Glendale st- Service Permit 9655. ID 72636	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/11/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 921 Glendale st- final Permit 9655. ID 72637	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/11/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 15 w Grand Final plumbing inspection Permit 9709 I'd 73276	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/12/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 212 n Mohawk Boiler replacement Permit 9786 I'd 73855	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/12/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 213 Walnut Rough plumbing inspection Permit 8676 I'd 63383	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/13/2020 - SFR Mechanical Inspection / David DeLeon 000203: 221 Walnut St - final 9481, 69630	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/13/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 233 Park St - final 9462, 69976	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/14/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 271 Addison Permit 9782 I'd 74058 Underground plumbing inspection	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/14/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 928 w Irving park Permit 9771 I'd 73670 Final boiler inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/14/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 920 w Irving park Permit 9772 I'd 73680 New boiler and water heater	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/14/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 922 W Irving park Permit 9773 I'd 73689 New boiler inspection	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 02/14/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 926 W Irving park Permit 9775 I'd 73785 Boiler and water heater inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/14/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 924 w Irving park Permit 9774 I'd 73698 Boiler inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/14/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 114 MASON - FINAL 9766, 73872	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/18/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 484 n Thomas- final building Permit 9474. ID 70167	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/19/2020 - SFR Building/Structural Inspection/ Jurtin Vide 002013: 1033 Daniel dr- final solar panels Permit 9779. ID 73675	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/19/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 411 s Dominic ct- rough Permit 8824. ID 64493	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/19/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 1033 Daniel dr- final solar panels Permit 9770. ID 73661	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/20/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 745 n birginal- final Permit 8608. ID 62890	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/20/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 745 n birginal- final Permit 8608. ID 62889	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/20/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 100 E Church club house Permit 9734. I'd 73864 Rough plumbing inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/20/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 745 N Birginal Permit 8608 I'd 62887 Final plumbing inspection	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 02/21/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 790 Maple - Service 9658, 74384	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/21/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 790 Maple - rough 9658, 72522	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/24/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 700 w golf In- final building racking Permit 9208. ID 67940	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/24/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 700 w golf In- final exit sings/em lights Permit 9208 ID 67941	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/24/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 271 s Addison Permit 9782 I'd 74055 Rough plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/25/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 23 grand Permit 9812 I'd 74421 Rough plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/25/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 23 grand ave Permit 9812 I'd 74165 Underground plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 02/27/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 840 S Addison Permit 9834 I'd 74386 Water heater inspection	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/28/2020 - SFR Mechanical Inspection / David DeLeon: 1002 Green Valley - final 9626, 72262	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 02/28/2020 - SFR Mechanical Inspection / David DeLeon: 253 Pine - final 9678, 72638	1.00	\$35.00	\$35.00

Amount Due **\$2,143.75** ✓
Ok, DL

Invoice

SAFEbuilt[®]

Invoice Number: 0067297-IN

Invoice Date: 03/31/20

Terms: Net 30 Days

Due Date: 04/30/20

Salesperson: SNO

Customer Number: 06-BENSNVL

Customer P.O.:

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

03312020BENSNVL-1

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHIL-BI - 03/02/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 951 n Thorndale- final /Permit 9139 ID 67755	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/03/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 208 s may st- final solar /Permit 9676. ID 72630	1.00	35.00	35.00
INSPECTIONS	4000-CECHIL-BI - 03/03/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 208 s may st- final solar /Permit 9676. ID 72713	1.00	35.00	35.00
INSPECTIONS	4000-CECHIL-BI - 03/03/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 720 w industrial- final fire alarm /Permit 9753. ID 73569	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/03/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1000 w industrial- final fire alarm /Permit 9616. ID 71175	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/04/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1130 n Ellis- final racking /Permit 9828. ID 74294	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/04/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 210 w Irving park- concrete piers /Permit 8451. ID 63259	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/05/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 321 w Irving park- final demo /Permit 9769. ID 7368	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/05/2020 - SFR Plumbing Inspection / Dan Witkowski / 271 S Addison 9782, 74056	1.00	35.00	35.00

Continued

REQUISITION # 20201331



Village of Bensenville

Invoice Number: 0067297-IN

Invoice Date: 03/31/20

Page: 2

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHIL-BI - 03/06/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 790 w maple ln /Permit 9658 l&e™d 73024 /Gas piping	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/06/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 271 Miner - final 9805, 74031	1.00	35.00	35.00
INSPECTIONS	4000-CECHIL-BI - 03/06/2020 - SFR Electrical Inspection / David DeLeon 000203: 271 S Miner - final 9805, 74042	1.00	35.00	35.00
INSPECTIONS	4000-CECHIL-BI - 03/06/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 14 N Center - final 9395, 69461	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/11/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 438 s county line- service /Permit 9754. ID 73552	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/17/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 106 W Foster /Permit 9725 l&e™d 73160 /Plumbing inspection	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/18/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 430 n Meyer- final windows /Permit 9804. ID 73998	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/18/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 405 s baron- garage floor pre pour /Permit 9648. ID 72962	1.00	35.00	35.00
INSPECTIONS	4000-CECHIL-BI - 03/18/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 405 s baron- slab on grade parking pad /Permit 9648. ID 72958	1.00	35.00	35.00
INSPECTIONS	4000-CECHIL-BI - 03/19/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1440 w Irving park- rough framing /Permit 9849. ID 74554	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/19/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 100 E George- rough framing /Permit 9734. ID 73866	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/19/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1440 w Irving park- rough /Permit 9849. ID 74552	1.00	43.75	43.75
INSPECTIONS	4000-CECHIL-BI - 03/19/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 100 e George- rough /Permit 9734. ID 73863	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0067297-IN

Invoice Date: 03/31/20

Page: 3

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHHL-BI - 03/20/2020 - MFR/Commercial Electrical Inspection / William Gleason 002608: 213 N Walnut Street - permit # 8676 - inspection ID # 63382	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/20/2020 - MFR/Commercial Mechanical Inspection / William Gleason 002608: 213 N Walnut Street - permit # 8676 - inspection ID # 66081	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/20/2020 - SFR Mechanical Inspection / William Gleason 002608: 255 S Center Street - permit # 9874 - inspection ID # 74732	1.00	35.00	35.00
INSPECTIONS	4000-CECHHL-BI - 03/20/2020 - MFR/Commercial Building/Structural Inspection / William Gleason 002608: 213 N Walnut Street - permit # 8676 - inspection ID # 63384	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/23/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 601 w frontier way- final /Permit 9749. ID 74611	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/25/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 314 s Hawthorne- concrete piers /Permit 8827. ID 65658	1.00	35.00	35.00
INSPECTIONS	4000-CECHHL-BI - 03/25/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 192 s center- final /Permit 9795. ID 73908	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/25/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 192 s center- final /Permit 9795. ID 73909	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/27/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 100 e George /Permit 9734 lã€™d 74803 /Rough plumbing	1.00	43.75	43.75
INSPECTIONS	4000-CECHHL-BI - 03/27/2020 - SFR Plumbing Inspecon / Dan Witkowski 002544: 615 Green /Permit 8900 lã€™d 66798 /Rough plumbing	1.00	35.00	35.00
INSPECTIONS	4000-CECHHL-BI - 03/27/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 615 Green - rough 8900, 66797	1.00	35.00	35.00
INSPECTIONS	4000-CECHHL-BI - 03/27/2020 - SFR Electrical Inspection / David DeLeon 000203: 615 Green - rough 8900, 66795	1.00	35.00	35.00
INSPECTIONS	4000-CECHHL-BI - 03/27/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 560 W Supreme Final 9846, 74767	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0067297-IN

Invoice Date: 03/31/20

Page: 4

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 03/30/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 352 s church- concrete piers fence /Permit 9872. ID 74723	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 03/31/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 352 s church- concrete piers fence /Permit 9872. ID 74832	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 03/31/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 540 n York- final guards and rails /Permit 9839. ID 74449	1.00	43.75	43.75

Amount Due

1,540.00

03312020BENS NVL-1

Remit Payment to:
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	<u>1,540.00</u>
Freight:	0.00
Sales Tax:	<u>0.00</u>
Invoice Total:	<u>1,540.00</u> ✓

Ok, DL

Invoice

SAFEbuilt.

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Terms: Net 30 Days

Due Date: 05/30/20

Salesperson: SNO

Customer Number: 06-BENSNVL

Customer P.O.:

04302020BENSNVL-1

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 04/01/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 736 n birginal-rough electric /Permit 9824, ID 74249	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/01/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 736 n birginal-gas piping /Permit 9824, ID 74673	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/01/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 114 w green st- soil erosion /Permit 9785, ID 73816	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/01/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 176 s rose st- final building /Permit. 9173, ID 67703	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/02/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 935 S Daniel dr /Permit 9858 /116674 74737 /New boiler installation	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 615 W Green - Rough HVAC 8900, 74854	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - SFR Electrical Inspection / David DeLeon 000203: 615 W Green - rough 8900, 74853	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 177 S Rose - 9882, 74782	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 800 Thorndale - piers 9826, 74286	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 802 Washington - 9884, 74787	1.00	35.00	35.00

Continued

5.8.20

REQUISITION # 20201464




Village of Bensenville

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Page: 2

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 1025 Donna - final 9830, 74322	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/03/2020 - SFR Electrical Inspection / David DeLeon 000203: 1025 Donna - final 9830, 74427	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/06/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 615 w Green /Permit tbd 75327  /Gas inspection	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/06/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 352 s church- final building fence /Permit 9872, ID 74726	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/07/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 317 s baron- final solar /Permit 9807, ID 74052	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/07/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 317 s Barron- final solar /Permit 9807, ID 74247	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/07/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 800 w second ct- final roof /Permit 9681, ID 72657	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/08/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 736 n birginal- final /Permit 9824, ID 74253	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/10/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 821 River Forest - 9881, 74799	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/10/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 460 W Irving Park - rough 9860, 74636 74632 	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/10/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 460 W Irving Park - rough 9860, 74630	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/10/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 10 Irving Park - 9859, 74755	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/10/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1130 S Thorndale - rough 9827, 74269	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/10/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1130 Thorndale - rough 9827, 74267	1.00	43.75	43.75

Continued



Village of Bensenville

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Page: 3

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 04/14/2020 - SFR Plumbing Inspection / Jim Kemper 000266: 527 GROVE ST; /INSPECTION 74700 /PERMIT 9867 /FINAL PLUMBING	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/14/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 201 s York rd- slab on grade service walk /Permit 5696. ID 42216	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 125 w grand ave- pavement subbase /Permit 9691. ID 72728	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 1016 w brookwood st- slab on grade /Permit 9815. ID 74216	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 321 green st- trench wall pre pour /Permit 9502. ID 70621	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 888 eagle dr- drop ceiling /Permit 9866. ID 74881	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 888 eagle dr- rough /Permit 9866. ID 74679	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 888 eagle - rough framing /Permit 9866. ID 74681	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/15/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 888 eagle dr. /Rough plumbing /74680	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/16/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 125 W Grand - base 9691, 75032	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/16/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 321 W Green - pre pour 9502, 75034	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/17/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 405 S Baron - final 9648 - 72472	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/17/2020 - SFR Electrical Inspection / David DeLeon 000203: 405 S Baron - 9648, 72691	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Page: 4

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 04/17/2020 - SFR Electrical Inspection / David DeLeon 000203: 405 S Baro. - UG 9648, 72959	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 888 eagle dr /Rough plumbing /9866, 75170	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 1130 w south Thorndale /Final plumbing /9827, 74270	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 1130 w Thorndale- final /Permit 9827, ID 74272	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 1130 Thorndale- above ceiling /Permit 9827, ID 74265	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1130 Thorndale- above ceiling /Permit 9827, ID 74266	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1130 Thorndale- final /Permit 9827, ID 74271	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1130 Thorndale- final /Permit 9827 ID 74273	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 405 s Barron- final /Permit 9648, ID TBD 75178	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 405 s Barron- final /Permit 9648, ID TBD 75177	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/20/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 114 e pine ave- concrete piers fence /Permit 9862, ID 74651	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/21/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 181 S Martha - drain tile 9887, 74829	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/21/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 501 E Red Oak -slab 8975, 66186	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Page: 5

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 04/21/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 501 E Red Oak - piers 8975, 66188	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/21/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1440 W Irving Park - final 9489, 74558	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/21/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1440 W Irving Park - final 9849, 74556	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/22/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 460 w Irving park- FINAL unit c UPS /PERMIT 9860. ID 74635	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/22/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 460 w Irving park- FINAL unit c UPS /PERMIT 9860. ID 74634	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/22/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 202 Jacquelyn- final /Permit 9573: ID 72559	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/23/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 361 N Marshall - pre pour 8814, 65874	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/23/2020 - SFR Plumbing Inspection / Ray Witkowski 002124: 172 Ridgewood /Drain line repair / sewer repair /75035	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/24/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 912 W Brookwood - drain tile 9888, 74883	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/24/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 772 E George - final 9806, 74053	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/24/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 1314 Glendale - 9912 74975	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/24/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 1312 Glendale - 9929 ID # 75108	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/27/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 321 w green- driveway pre pour /Permit 9502. 70622	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/27/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 321 w green- pre pour concrete steps /Permit 9502. ID 75221	1.00	35.00	35.00

Continued



Village of Bensenville

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Page: 6

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4000-CECHI-IL-BI - 04/27/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 317 w green- driveway pre pour /Permit 9501 ID 70619	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/28/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 231 s miner- final solar, /Permit 9800, ID 73935	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/28/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 234.s James- final pavement /Permit 9901, ID 74914	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/28/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 231 s miner- final solar /Permit 9800, ID 73951	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/29/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 888 Eagle /permit 9866 ID 74682 /final Plumbing	0.50	43.75	21.88
INSPECTIONS	4000-CECHI-IL-BI - 04/29/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 113 E Jacqueline - final 9905, 74933	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/29/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 343 S Walnut - slab, 9904, 74931	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/29/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 888 Eagle - final 9866, 74684	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/29/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 888 Eagle - final 9866, 74683	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/30/2020 - SFR Plumbing Inspection / Ray Witkowski 002124: 172 Ridgewood /Sewer Repair /9923, 75262	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/30/2020 - SFR Plumbing Inspection / Ray Witkowski 002124: 314 Mason /Sewer Repair /9875, 74738	1.00	35.00	35.00
INSPECTIONS	4000-CECHI-IL-BI - 04/30/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 430 Country Club - final 9724, 73066	1.00	43.75	43.75
INSPECTIONS	4000-CECHI-IL-BI - 04/30/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 971 Supreme - final 9825, 74260	1.00	43.75	43.75

Amount Due

2,979.38

04302020BENSNVL-1

Remit Payment to: SAFEbuilt, LLC
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	2,979.38
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	2,979.38

dy
OK



Village of Bensenville

Invoice Number: 0068265-IN

Invoice Date: 04/30/20

Page: 7

Item Type	Description	Qty	Unit Price	Amount
-----------	-------------	-----	------------	--------

Remit Payment to: SAFEBuilt, LLC
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	2,979.38
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	2,979.38

OK
✓

Invoice



Invoice Number: 0068264-IN

Invoice Date: 04/30/20

Terms: Net 30 Days

Due Date: 05/30/20

Salesperson: SN0

Customer Number: 06-BENSNVL

Customer P.O.:

04302020BENSNVL-2

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Item Type	Description	Qty	Unit Price	Amount
PLAN REVIEW	4250-CECHI-IL-PR - 04/23/2020 - MFR/Commercial Addition 7501 to 10,000 sf (building + 3 disciplines) / Gerald Keys 001730: 904 West Irving Park Rd - new carwash -Application #9926 - 1st review - Not Approved	1.00	1,580.00	1,580.00
PLAN REVIEW	04/23/2020 - MFR/Commercial Addition 7501 to 10,000 sf (building + 3 disciplines) / Gerald Keys 001730: 904 West Irving Park Rd - new carwash -Application #9926 - 1st review - Not Approved	1.00	1,400.00	1,400.00
Amount Due				2,980.00

04302020BENSNVL-2

Remit Payment to: SAFEbuilt, LLC
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	2,980.00
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	2,980.00

05/01/20
VPL

Invoice



Invoice Number: 0068872-IN

Invoice Date: 05/31/20

Terms: Net 30 Days

Due Date: 06/30/20

Salesperson: SN0

Customer Number: 06-BENSNVL

Customer P.O.:

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

05312020BENSNVL-1

Item Type	Description	Qty	Unit Price	Amount
INSPECTIONS	4250-CECHIL-PR - 05/28/2020 - SFR Addition >500sf / Gerald Keys 001730: 1211 Glendale - Addition	1.00	420.00	420.00
Amount Due				420.00 ✓

05312020BENSNVL-1

Remit Payment to: SAFEBuilt, LLC
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	420.00
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	420.00

OK
V.D.



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **05312020BENSNVL-1**
Issue Date **06/01/2020**
Due Date **07/01/2020 (Net 30)**
Subject **VILLAGE OF BENSENVILLE PLAN REVIEW
SERVICES - MAY 2020**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106


Item Type	Description	Quantity	Unit Price	Amount
Inspections	4250-CECHI-IL-PR - 05/28/2020 - SFR Addition >500sf / Gerald Keys 001730: 1211 Glendale - Addition	1.00	\$420.00	\$420.00

Amount Due \$420.00

SAFEbuilt®

From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **05312020BENSNVL-2**
Issue Date **06/01/2020**
Due Date **07/01/2020 (Net 30)**
Subject **VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - MAY 2020**



Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 05/06/2020 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 100 E George - rough 9734, 73865	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/07/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 759 Industrial - plers 9729, 73343	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/08/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1156 S York - final 9817, 74296	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/08/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 16W608 third st Permit 9937 Inspection 75195 Sewer repair	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/12/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 220 Gateway - slab 9930, 75212	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/12/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 800 Thorndale - final 9826, 74264	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/12/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 800 Thorndale - final 9826, 74287	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/12/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 317 Green - final 9501, 70620	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/12/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 321 Green - final 9502, 70623	1.00	\$35.00	\$35.00

REQUISITION. 20202088
7-7-20

Inspections	4000-CECHI-IL-BI - 05/13/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 759 Industrial - final 9729, 73120	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/13/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 202 E Jacqueline - 9573, 72559	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/14/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 248 S Miner - final 9880, 74776	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/14/2020 - SFR Electrical Inspection / David DeLeon 000203: 248 Miner - final 9880, 75171	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/14/2020 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 411 S Domenic - 8824, 70601	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/14/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 411 S Domenic - 8824, 64498	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/14/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 411 S Domenic - slab 8824, 70603	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/14/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 411 S Domenic - ceiling 8824, 70602	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/14/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 411 S Domenic - final 8824, 64497	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/14/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 411 Dominic ct Final plumbing 8824, ID 64496	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/15/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 821 River Forest - final 9881, 74800	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/15/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 813 S River Forest - final 9915, 74987	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/15/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1130 Thorndale - final 9950, 75279	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 05/18/2020 - SFR Mechanical Inspection / David DeLeon 000203: 865 Brentwood - final 8899, 65327	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/18/2020 - SFR Electrical Inspection / David DeLeon 000203: 865 Brentwood - final 8899, 65326	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/18/2020 - SFR Electrical Inspection / David DeLeon 000203: 317 E Jefferson - final 9713, 73014	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/18/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 317 E Jefferson - final 9713, 72932	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/19/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 132 s Addison- underground Permit 9925. ID 75263	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/19/2020 - SFR Mechanical Inspection / Jurtin Vide 002013: 865 Brentwood ct- NEW SFR final PERMIT 8899. ID 75601	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/19/2020 - SFR Electrical Inspection / Jurtin Vide 002013: 865 Brentwood ct- NEW SFR final PERMIT 8899. ID 75600	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/21/2020 - SFR Plumbing Inspecon / Ray Witkowski 002124: 314 s hawthorn Final 65654	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/21/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 314 Hawthorne - final 8827, 65656	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/21/2020 - SFR Mechanical Inspection / David DeLeon 000203: 314 Hawthorne - final 8827, 64554	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/21/2020 - SFR Electrical Inspection / David DeLeon 000203: 314 Hawthorne - final 8827; 65655	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/22/2020 - SFR Plumbing Inspecon / Ray Witkowski 002124: 865 Brentwood ct Final plumbing 65325	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/22/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1440 Irving Park - Final 9849, 75194	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/22/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1440 W Irving Park - final 9849, 75193	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 05/22/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 490 Supreme - final 9909, 74957	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/22/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 490 Supreme - final 9909, 74952	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/22/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 490 Supreme - final 9909, 74956	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/22/2020 - SFR Electrical Inspection / David DeLeon 000203: 615 Green - insulation 8900, 75209	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/22/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1010 Foster - final 9891, 74839	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/26/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 460 S County Line Rd - final 9813, 74107	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/27/2020 - MFR/Commercial Plumbing Inspection/ Dan Witkowski 002544: 100 E George Permit 9734 I'd 73867 Final plumbing inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/27/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 428 Miner - Slab 9856, 75118	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/27/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 631 W Mclean - Post holes 9938, 75214	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/27/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 205 S Miner - post holes 9956, 75560	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/27/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 114 W Green - footing 73820, 9785	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/27/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 903 S York - final 8937, 75667	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/27/2020 - SFR Mechanical Inspection / David DeLeon 000203: 903 S York - final 8937, 75666	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 05/27/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 640 County Line - foundation 9813, 74108	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/27/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 100 E George - final 9852, 74698	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/28/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 100 E George - final 9880, 73870	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/28/2020 -MFR/Commercial Electrical Inspection n / David DeLeon 000203: 100 E George, final 9734, 73868	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/28/2020 - SFR Electrical Inspection / David DeLeon 000203: 248 Miner - final 9880, 75553	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/28/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 248 Miner - final 9880, 75533	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/28/2020 - SFR Mechanical Inspection / David DeLeon 000203: 100 George - final 9734, 73869	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/28/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 344 Mason - base 9993, 75554	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/28/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 640 county line Rd - footing 9813, 74107	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 05/29/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 865 Brentwood ct Permit 8899 I'd 75664 Final plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/29/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 927 Pamela - pre pour 9879, 74762	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/29/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 205 Miner - slab 9945, 75244	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 05/29/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 640 County Line - pre pour 9813, 75707	1.00	\$43.75	\$43.75

Amount Due

\$2,432.50

OK
DL

Invoice



Invoice Number: 0070381-IN

Invoice Date: 06/30/20

Terms: Net 30 Days

Due Date: 07/30/20

Salesperson: SNO

Customer Number: 06-BENSNVL

Customer P.O.:

06302020BENSNVL-1

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

Item Type	Description	Qty	Unit Price	Amount
PLAN REVIEW	4250-CECHI-IL-PR - 06/26/2020 - MFR/Commercial Addition 10,001 sf (building + 3 disciplines) / Gerald Keys 001730: 1010 West Foster Ave - Non-Residential alteration - 1st review - Approved with notes	1.00	1,950.00	1,950.00
PLAN REVIEW	4250-CECHI-IL-PR - 06/26/2020 - Each 1000sf over 10,000 - building + 3' disciplines / Gerald Keys 001730: 1010 West Foster Ave - Non-Residential alteration - 1st review - additional 3,295 sf (4,000 sf).	4.00	40.00	160.00

Amount Due

2,110.00*ok*
D.L.

06302020BENSNVL-1

Remit Payment to: SAFEBuilt, LLC
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	2,110.00
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	<u>2,110.00</u>



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **06302020BENSNVL-1**
Issue Date **07/01/2020**
Due Date **07/31/2020 (Net 30)**
Subject **VILLAGE OF BENSENVILLE PLAN REVIEW -
JUNE 2020**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Plan Review	4250-CECHI-IL-PR - 06/26/2020 - MFR/Commercial Addition 10,001 sf (building + 3 disciplines) / Gerald Keys 001730: 1010 West Foster Ave - Non-Residential alteration - 1st review - Approved with notes	1.00	\$1,950.00	\$1,950.00
Plan Review	4250-CECHI-IL-PR - 06/26/2020 - Each 1000sf over 10,000 - building + 3 disciplines / Gerald Keys 001730: 1010 West Foster Ave - Non-Residential alteration - 1st review - additional 3,295 sf (4,000 sf).	4.00	\$40.00	\$160.00

Amount Due \$2,110.00

Revised June 2020 Invoice



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **06302020BENS NVL-2**
Issue Date **07/01/2020**
Due Date **07/31/2020 (Net 30)**
Subject **VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - JUNE 2020**

Invoice For **06-BENS NVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 06/01/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 205 Miner - post holes 9956, 75709	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/01/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 640 County Line Rd - foundation 9813, 75747	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/01/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 220 N Church - 9822, 74434	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/01/2020 - SFR Electrical Inspection / David DeLeon 000203: 220 N Church - final 9822, 74428	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/01/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 306 Red Oak - final 9960, 75339	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/01/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 220 Church permit 9822 id 74430 rough Plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/02/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 640 s county line- foundation pre pour Permit 9813 ID 75759	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/03/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 790 Maple - final 9658, 72527	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/03/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 790 Maple - final 9658, 72526	1.00	\$43.75	\$43.75

Requisition # 20202649 Page 1 of 8

Inspections	4000-CECHI-IL-BI - 06/03/2020 - SFR Electrical Inspection / David DeLeon 000203: 220 Church - rough 9822, 75783	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/05/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 640 county line permit 9813 id 74115 underground Plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/05/2020 - SFR Electrical Inspection / David DeLeon 000203: 607 W Green - final 9936, 75217	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/05/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 607 W GREEN - FINAL 9936, 75192	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/05/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 111 E PAMELA - FINAL 9997, 75576	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/08/2020 - SFR Plumbing Inspection / Ray Witkowski 002124: 220 church Final plumbing 75829	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/08/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 114 W GREEN - 9785, 73821	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/08/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1440 W IRVING PARK - FINAL 9849, 75675	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/08/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 865 S BRENTWOOD - FINAL 8899, 65328	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/11/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 361 n Marshall Final 65879	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/11/2020 - SFR Plumbing Inspection / Ray Witkowski 002124: 220 church Final plumbing 75903, ID#9822	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/11/2020 - SFR Electrical Inspection / Ray Witkowski 002124: 220 church Final electrical 74429, ID #9822	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 06/11/2020 - SFR Building/Structural Inspection / Ray Witkowski 002124: 218 tioga Rough framing 74950, ID #9908	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/11/2020 - SFR Building/Structural Inspection / Ray Witkowski 002124: 218 tioga Final 74951, ID #9908	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/11/2020 - SFR Electrical Inspection / Ray Witkowski 002124: 218 tioga Final 74960, ID #9908	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/12/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 865 s Brentwood Permit 8899 I'd 75664 Final plumbing inspection	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/12/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 224 N MOHAWK 9996, 75648	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/12/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 865 BRENTWOOD 8899, 75904	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/12/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1130 N ELLIS 1008, 75639	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/15/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 100 E GEORGE, 9820, 74815	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/15/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 100 E GEORGE 9820, 74813	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/15/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 126 ADDISON 9919, 75031	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/15/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 1317 MEDINAH 9854, 74595	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/15/2020 - SFR Electrical Inspection / David DeLeon 000203: 1317 MEDINAH 9854, 74735	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 06/16/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 10 e pine- slab on grade Permit 10002. ID 75610	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/16/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1050 s county line- slab on grade Permit 8877. ID 65076	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/17/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 361 MARSHALL 8814, 75964	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/17/2020 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 361 MARSHALL - 8814, 75966	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/17/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 361 MARSHALL 8814, 75965	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/17/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 860 Eagle Dr aplication 10070 id 76019 plan review	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/17/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 410 E.Pine ave id 75986 plan review	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/18/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 114 W GREEN 9785, 75905	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/18/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 116 FORESTVIEW - 9998, 75591	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/18/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 116 FORESTVIEW 9998, 75590	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1050 COUNTY LINE RD - 8877, 76116	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1153 ELLIS - 10022, 75716	1.00	\$43.75	\$43.75

Inspections	4000-CECHI-IL-BI - 06/19/2020 - SFR Electrical Inspection / David DeLeon 000203: 220 N CHURCH - 9822, 76202	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1010 JUDSON - 9946, 75259	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1010 JUDSON - 9946, 75255	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1153 ELLIS 10022, 75714	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/19/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 220 N.Church permit 9822 id 76006 rough plumbing insp	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1153/5 N.Ellis permit 10022 id 75715 Rough Plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/19/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1153/5 N.Ellis permit 10022 id 75901 underground	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/23/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 1050 s county line- above ceiling electric/hvac Permit 8877 ID 65084	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/23/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 640 s county line- rough framing partial Permit 9813. ID 74128	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/24/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 991 Supreme - 9927, 75832	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/24/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 860 Thomas - slab 10023, 75840	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/24/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 184 Rose - 9779 73857	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 06/24/2020 - SFR Electrical Inspection / David DeLeon 000203: 184 Rose 9779, 73755	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/24/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 219 E Pine Permit tbd I'd tbd Fold inspection	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/24/2020 - SFR Mechanical Inspection / Dan Witkowski 002544: 49 Dennis dr Permit tbd Id. Tbd Site inspection	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/25/2020 - SFR Plumbing Inspeccion / Ray Witkowski 002124: 220 Church Final Plumbing 74431	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 860 Eagle dr permit 10070 Id 76266 slab on grade inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/26/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 860 Eagle dr permit 10070 ID 76265 underground plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 201 s. York unit 201 permit 5696 ID 42292 final Plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 201 S.York unit 203 permit 5696 Id 42293 final Plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 201S.York Unit 205 permit 5696 ID 42294 final Plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 201 S.York unit 207 permit 5696 id 42295 final Plumbing	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Plumbing Inspection / Dan Witkowski 002544: 201 S.York unit 209 permit 5696 ID 42296 final Plumbing	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 220 N CHURCH - 9822, 76402	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 201 S YORK - 5696, 42228	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 201 S YORK - 5696, 42278	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 201 S YORK - 5696, 42279	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 201 S YORK - 5696, 42280	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 201 S YORK - 5696, 42281	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Mechanical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42287	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Mechanical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42288	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Mechanical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42289	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Mechanical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42290	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Mechanical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42291	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Electrical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42229	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Electrical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42282	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Electrical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42283	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Electrical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42284	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Electrical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42285	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - SFR Electrical Inspection / David DeLeon 000203: 201 S YORK - 5696, 42286	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 06/26/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1153 ELLIS - 10022, 75712	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/26/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1153 ELLIS - 10022, 75713	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/29/2020 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 430 N COUNTRY CLUB - 9757, 73430	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/29/2020 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 430 N COUNTRY CLUB 9724, 73067	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/29/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 430 Country Club Dr permit 9724 Id 73065 final plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/30/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 1153 Ellis st- slab on grade Permit 10022. ID 75876	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 06/30/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 401 w eastern ave- rough electric Permit 10041. ID 75833	1.00	\$43.75	\$43.75

Amount Due

\$3,543.75

OK
✓DL.

Invoice

SAFEbuilt®

Invoice Number: 0071118-IN

Invoice Date: 07/31/20

Terms: Net 30 Days

Due Date: 08/30/20

Salesperson: SN0

Customer Number: 06-BENSNVL

Customer P.O.:

Village of Bensenville
Attn: Dean Lawrentz
12 S Center Street
Bensenville, IL 60106

07312020BENSNVL-2

Item Type	Description	Qty	Unit Price	Amount
PLAN REVIEW	4250-CECHI-IL-PR - 07/31/2020 - Each 1000sf over 10,000 - building only / Gerald Keys 001730: 350 N York Rd Bensenville - Fire alarm - 1st rev - Conditionally Approved	2.00	20.00 90.00	40.00 180.00

Amount Due

~~40.00~~ 180.00

OK ✓ OL

SEE ATTACHED
EMAIL.

07312020BENSNVL-2

Remit Payment to:
3755 Precision Dr, Suite 140 Loveland, CO 80538

Net Invoice:	40.00
Freight:	0.00
Sales Tax:	0.00
Invoice Total:	40.00

180.00

OK ✓ OL

Dean Lawrentz

From: Keith Rooney <krooney@safebuilt.com>
Sent: Wednesday, August 19, 2020 7:57 AM
To: Dean Lawrentz
Cc: David DeLeon; Kati Vokovitch
Subject: Fire plan review invoice

Dean,

I'm working on trying to get an invoice to you for the fire review we did. We don't have anything in our billing system yet that allows us to bill for this work as we are not allowed to update the billing software until we have a signed contract in hand.

The data we need would have been programmed in as part of the changes to the current contract but as Scott has notified us that the work will be going to RFP, it looks as though we will not be getting the new contract.

I have asked Kati to figure out a way to bill it as a standard non-residential review and she will work on that for you, but it may take a little time. If it helps your current situation, ~~the invoice will be \$180.00 for that review. (2 hours @ \$90/Hour)~~

Thanks,

Keith Rooney, MCP
Illinois Operations
SAFEbuilt, Illinois
(224)477.6954
krooney@safebuilt.com

SAFEbuilt.

REVISED July 2020 INVOICE



From **SAFEbuilt IL**
SAFEbuilt
Attn: Mike Garcia
3755 Precision Drive, Suite 140
Loveland, CO 80538

Invoice ID **07312020BENSNVL-1**
Issue Date **08/01/2020**
Due Date **08/31/2020 (Net 30)**
Subject **VILLAGE OF BENSENVILLE BUILDING
INSPECTION SERVICES - JULY 2020**

Invoice For **06-BENSNVL**
Village of Bensenville
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Item Type	Description	Quantity	Unit Price	Amount
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 361 N Marshall a/b permit 8814 ID 76213 final Plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 860 E Eagle dr permit 10070 Id 76011 rough	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1153 N.Ellis permit 10022 Id 75717 final Plumbing Inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 229 grand - 9791, 73877	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1153 Ellis 10022, 75719	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1153 Ellis - 10022, 75877	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 1153 Ellis - 10022, 75720	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 1153 Ellis - 10022, 75718	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/01/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 229 Grand - 9791, 73890	1.00	\$43.75	\$43.75

REQUISITION # 2020 2651 Page 1 of 7

Inspections	4000-CECHI-IL-BI - 07/02/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 860 Eagle Dr perm 10070 id 76526 rough Plumbing inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/02/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 860 Eagle dr permit 10070 id 76009 final inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/02/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 114 Green 9785, 76508	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/02/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 659 Supreme 1011, 76525	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/02/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 659 Supreme - 1011, 76558	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/02/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 659 Supreme - 1011, 75656	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/06/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 237 Walnut 10104, 76385	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/06/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 846 Green. - 9986, 76542	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/06/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 114 Green 9785, 76546	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/07/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 401 eastern ave- final Permit 10041. ID 75837	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/09/2020 - MFR/Commercial Building/Structural Inspection / Keith Rooney 002272: 237 Walnut Street - Final Fences, #10104, ID 16386	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/09/2020 - SFR Building/Structural Inspection / Keith Rooney 002272: 840 Addison - Concrete Pre Pour, Patio Walks and Piers - #10005, ID 75621	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/09/2020 - SFR Building/Structural Inspection / Keith Rooney : 840 Addison - Slab on Grade- #10005, ID 75980	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 07/13/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 736 N BIRGINAL - FINAL 9824, 74254	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/13/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 343 PARK - FINAL 9463, 70857	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/16/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 350 York Rough plumbing 10073, 76024	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/16/2020 - SFR Plumbing Inspection / Ray Witkowski 002124: 212 Mohawk Final plumbing 9786, 74414	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/16/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 350 N YORK - FRAMING 10073, 76025	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/16/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 350 N YORK - ROUGH 10073, 76023	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/20/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 100 E GEORGE PERMIT 9957 ID 76186 ROUGH PLUMBING	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/20/2020 - MFR/Commercial Building/Structural Inspection/ Dan Witkowski 002544: 100 E GEORGE PERMIT 9957 ID 75318 SLAB ON GRADE CONCRETE PRE POUR	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/20/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 404 CENTER - FINAL 10087, 76221	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/21/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 271 s Addison- draintile Permit 9847. ID 74610	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/21/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 775 w hillside- concrete piers Permit 10115. ID 76229	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/21/2020 - SFR Building/Structural Inspection / Jurtin Vide 002013: 604 e Jefferson- final fence Permit 9995. ID 75563	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 07/21/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 659 w supreme- drop ceiling mechanical Permit 10011. ID 75654	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/21/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 321 w Irving- footing pre pour partial Permit 993. ID 75126	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/21/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 659 w supreme- drop ceiling Permit 10011. ID 75655	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/22/2020 - SFR Building/Structural Inspection / Dan Witkowski 002544: 951 DOLORES PERMIT 10053 ID 75913 PRE POUR OST HOLES	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/22/2020 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 321 W IRVING PARK PERMIT 9931 ID 76891 NEW CONSTRUCTION FOOTING	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/22/2020 - MFR/Commercial Building/Structural Inspection / Dan Witkowski 002544: 511 W IRVING PARK RD PERMIT 9853 ID 74585 FENCE HOLES PRE POUR	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/22/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 100 E GEORGE - FRAMING 9957, 75321	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/22/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 214 POPPY - DEMO 10101, 76359	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/24/2020 - MFR/Commercial Mechanical Inspection / Dan Witkowski 002544: 205 S.Park permit 10164 id 76676 final mechanical RTU	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/24/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 213 N.Walnut permit 8676 ID 63385 final Plumbing	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/24/2020 - SFR Plumbing Inspeccion / Dan Witkowski 002544: 410 pine permit10037 id 76164 sewer underground	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 07/24/2020 - MFR/Commercial Mechanical Inspection / Dan Witkowski 002544: 205 S.Park permit10164 id 76675 final electrical connections	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/24/2020 - SFR Building/Structural Inspection / Dan Witkowski 002544: 228 S.York permit 10122 id 76390 slab on grade	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/24/2020 - SFR Building/Structural Inspection / Dan Witkowski 002544: 228 S.York permit 9523 id 70774 final fence,patio and walk way concrete	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/24/2020 - SFR Building/Structural Inspection / Dan Witkowski 002544: 321 W.Wood. permit 10154 id 76617 slab on grade pre pour	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/24/2020 - SFR Electrical Inspection / David DeLeon 000203: 949 BREITER CT - 10158 76647	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/24/2020 - SFR Building/Structural Inspection / David DeLeon 000203: 949 BREITER CT - 10158 76643	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/24/2020 - MFR/Commercial Mechanical Inspection / David DeLeon 000203: 213 WALNUT - FINAL 8676, 63387	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/24/2020 - MFR/Commercial Building/Structural Inspection / David DeLeon 000203: 213 WALNUT FINAL - 8676, 63388	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/24/2020 - MFR/Commercial Electrical Inspection / David DeLeon 000203: 213 WALNUT FINAL - 8676, 63386	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/27/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 1010 w Foster Permit 10091 I'd 76475 Underground plumbing inspection	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/27/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 350 n York-insulation Permit 10073. ID 76117	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/30/2020 - SFR Building/Structural Inspection / Anthony Wesbrook 002226: 202 S MASON ST. BASEMENT FLOOR PREPOUR 10085 76231 APPROVED	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 07/28/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 228 w William- slab on grade Permit 10116. ID 76327	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/28/2020 - MFR/Commercial Mechanical Inspection / Jurtin Vide 002013: 659 w supreme-final Permit 10011 ID 75661	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/28/2020 - MFR/Commercial Building/Structural Inspection / Jurtin Vide 002013: 649 w supreme- final Permit 10011. ID 75662	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/28/2020 - MFR/Commercial Electrical Inspection / Jurtin Vide 002013: 659 w supreme- final Permit 10011. ID 75660	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/29/2020 - MFR/Commercial Building/Structural Inspection / Anthony Wesbrook 002226: 1010 W. FOSTER AVE. SLAB ON GRADE PRE-POUR 10091 76956 FAILED - NOT READY	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/29/2020 - MFR/Commercial Building/Structural Inspection / Anthony Wesbrook 002226: 228 W. WILLIAM ST FOUNDATION WALL PRE-POUR 10116 76326 APPROVED	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/29/2020 - SFR Building/Structural Inspection / Anthony Wesbrook 002226: 846 W. GREEN STREET ROUGH FRAMING - DECK 9986 77053 PARTIALLY APPROVED	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/30/2020 - MFR/Commercial Plumbing Inspection / Ray Witkowski 002124: 100 e George Rough plumbing 9957, 75320	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/30/2020 - SFR Building/Structural Inspection / Anthony Wesbrook 002226: 212 MOHAWK DRIVE FINAL BLDG. - SOLARS 10074 76035 APPROVED	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/30/2020 - MFR/Commercial Building/Structural Inspection / Anthony Wesbrook 002226: 27 W. GRAND AVE FINAL SIGNS 9790 73876 APPROVED	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/30/2020 - SFR Building/Structural Inspection / Anthony Wesbrook 002226: 202 S MASON ST. DRAIN TILE 10085 76232 APPROVED	1.00	\$35.00	\$35.00
Inspections	4000-CECHI-IL-BI - 07/30/2020 - SFR Electrical Inspection / Anthony Wesbrook 002226: 212 MOHAWK DRIVE FINAL - SOLARS 10074 76038 APPROVED	1.00	\$35.00	\$35.00

Inspections	4000-CECHI-IL-BI - 07/30/2020 - MFR/Commercial Electrical Inspection / Anthony Wesbrook 002226: 27 W. GRAND AVE FINAL - SIGNS 9790 73930 APPROVED	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/31/2020 - MFR/Commercial Building/Structural Inspection / Anthony Wesbrook 002226: 860 N THOMAS FINAL 10023 75731 APPROVED	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/31/2020 - MFR/Commercial Building/Structural Inspection / Anthony Wesbrook 002226: 991 SUPREME DR. FINAL BUILDING 9927 75091 FAILED. 1-STAIRWAY DOES NOT MEET IBC & ACCESSIBILITY REQUIREMENTS.	1.00	\$43.75	\$43.75
Inspections	4000-CECHI-IL-BI - 07/31/2020 - MFR/Commercial Plumbing Inspection / Dan Witkowski 002544: 321 W IrvingPark rd Permit 9931 I'd 75140 Water service inspection	1.00	\$43.75	\$43.75

Amount Due \$3,001.25

OK
V.D.L.

Proposal for

*Professional Residential,
Mixed Use, and Commercial Plan
Review & Inspectional Services
Bensenville, IL*

September 18, 2015



Steve Nero
Business Development
847.656.5350
smartin@safebuilt.com

Steve Touloumis
Operations Manager
224.277.1073
stouloumis@safebuilt.com

All information contained in this document shall be treated as proprietary and confidential.

September 18, 2015

Mark Rysavy
Assistant Director
Community & Economic Development
12 South Center Street
Bensenville, IL 60106

Dear Mr. Rysavy:

SAFEbuilt Illinois, LLC (SAFEbuilt) is pleased to present our proposal in response to the request for Professional Residential, Mixed Use, and Commercial Plan Review & Inspectional Services in the Village of Bensenville. Accurate and timely plan reviews and inspections are critical to support Village development. SAFEbuilt provides efficient and effective solutions to keep projects on schedule. Our proven methods deliver high customer satisfaction at a reasonable cost.

In order to provide the support needed for Bensenville, it is imperative to choose a contractor with proven abilities that is capable of fully understanding the nature of these types of projects. Through our experience with Illinois communities, as well as projects all over the United States, SAFEbuilt has a complete understanding of the requirements. We have demonstrated our capabilities with many projects of similar size, scope, and complexity. SAFEbuilt is a local partner with the capacity to customize services to meet your needs. Our office is approximately five miles from Bensenville, making it easy for us to give exemplary service on your project needs.

SAFEbuilt has been providing similar services in Illinois since 2013. We are currently working in Dekalb, Glenview, Willmette, Winnetka, Itasca, Downers Grove, and Evanston – to name just a few. We are fully qualified to provide the services requested and are excited about this opportunity to forge a partnership. We look forward to meeting with you in regards to the details of our proposal and the benefits of choosing SAFEbuilt as your partner for Professional Residential, Mixed Use, and Commercial Plan Review & Inspectional Services.

Best,



Steve Nero
Business Development
SAFEbuilt
847.656.5350
snero@safebuilt.com

Table of Contents

Table of Contents.....	2
A. Introduction.....	3
Overview of Services.....	5
B. Qualifications	8
Corporate Organization	8
Recent Experience with Similar Projects	9
Transition Experience	10
Recent Firm Experience in Surrounding Areas near Bensenville	16
C. Schedule	17
Reporting.....	17
D. Costs.....	18
Community Outreach Programs.....	20
Why SAFEbuilt?.....	21
E. References	22
Client List.....	23
F. Sample Work.....	25
G. Start Date.....	44
H. Point of Contact.....	45

A. Introduction

Executive Summary

For six consecutive years, SAFEbuilt has maintained a client satisfaction rating of 97% or higher. Client satisfaction starts with understanding our clients' needs and customizing programs to meet those specific needs. We believe our response will provide you with the information needed to show that SAFEbuilt is well qualified to deliver outstanding contract performance for the Village of Bensenville. Outlined below are our high level goals for our proposed approach to address Bensenville's contractual needs.

Smooth Transition of Services

When transitioning to a new team, we have discovered that potential clients are often concerned with the impact on their team and the community they serve. Current employees, additional departments, permit holders, applicants, and other jurisdictions are all affected by the decision. SAFEbuilt has helped guide jurisdictions through this process many times during our 22 years in business. We have a team of professionals dedicated to this effort and have developed processes that ensure the needs of all stakeholders are met and services are never interrupted. While the process may appear overwhelming, we have been able to eliminate most uncertainty through our long-term experience. Our team begins by meeting with an assigned point person in Village, followed by making a site visit to review the current facility, technical and environmental details, current operations,

system capabilities, and any other relevant requirements. Prior to start date, SAFEbuilt works to coordinate details and review status with the Village to ensure implementation approval and answer questions. Working together, we have the ability to customize our procedures to ensure everyone involved is satisfied with the outcomes we deliver.



Improved Service Delivery

SAFEbuilt has a proven track record of streamlining internal workflow coordination, as well as clearly identifying working relationships that will assist in improving efficiency. From the start of each contract, our transition team works with Village staff to customize best practices in a manner that most aligns with Village goals. While various aspects of Village contracts must be consistent from location to location, SAFEbuilt understands that no two community programs are identical. Therefore, we tailor our programs and processes to meet local needs.

In addition to process innovations, our team is experienced with the ebb and flow of workload activity associated with building

permits due to seasonal and economic factors. We have numerous offices in Illinois that provide building department services, and we are able to float resources as needed to meet current activity demands.



Fostering a Professional Image

SAFEbuilt will handle all of Bensenville's commercial projects with great professionalism, just as we currently do in our partner communities in Illinois. It is our goal to work seamlessly and concurrently with Village staff. With over 20 years' experience, our team of certified professionals will ensure the building department services in Bensenville are delivered efficiently and consistently. Our experience in the field, coupled with our appropriate use of technology and robust business systems ensures that deadlines are always met, and expectations are exceeded. Our model offers the benefits of a centralized service center, while also allowing communities to maintain local control and identity. We understand the need for high

levels of professionalism and customer satisfaction for our services.

Ability to Supply Personnel to Meet Demand Fluctuations

Our model offers some real advantages to Bensenville by providing flexibility and a sense of security knowing that reliable expertise is always on hand, without the hassle of the staffing issues or fixed costs that come with an in-house department. As an outside firm providing services to other Illinois municipalities, we are able to address municipal needs, such as staffing, appropriately. We have the capability to easily increase or decrease employee size through our scheduling process on a daily basis.

Our service delivery is number one. If an increase appears to be permanent, we simply bring in additional full time staff and ensure we have part time staff ready for the next possible surge or absences. This works for our agency, because we have no headcount restrictions, political objectives, or union issues. Bensenville gains access to a deep network of experienced building officials, plans examiners, trade inspectors, and more. SAFEbuilt assumes responsibility for all staffing issues. We manage the workload and hiring process, as well as provide salaries, benefits, ongoing training, and vehicles for staff.

Overview of Services

Per your request, below is an overview of the services SAFEbuilt will provide. We are fully familiar with these functions and capable of providing these services to Bensenville.

Building, Plumbing, Mechanical, and Electrical Inspection Services

Our inspection staff recognize that an educational, informative approach is the most effective way to improve the customer's experience. The following highlights some of the important factors that are taken into account when having SAFEbuilt perform Inspection Services.



Time Frame for Inspections and Management of Inspector Schedules

We will sit down with the Village to establish a customized Inspection Notification Process. SAFEbuilt offers next day inspections for any request received by 4:30PM on the prior business day. We offer weekend and after hours inspections on a scheduled basis for an additional fee. We also do not charge for inspections related to emergencies or Village projects. SAFEbuilt uses a routing program that utilizes computer mapping and GPS to route inspections efficiently. Homeowners who pull a permit may call to schedule an

appointment window of two-hours in order to minimize the time they need to be home.

Types of Inspections to be Performed

SAFEbuilt operations conduct Building, Mechanical, Electrical, and Plumbing Inspections for building related permits. We also conduct Rental Housing and Code Enforcement Inspections. Our inspection lists for each type of permit in the community are developed based on the adopted codes, as well as specific requirements from the Village.

Details on Inspection Request Process

Inspections in all SAFEbuilt offices can be requested by traditional methods of phone, email, or fax. Requests will always be handled promptly and professionally. All inspection requests received by 4:30PM will be performed on the next business day. We also offer special inspections and after hour inspections upon request.

SAFEbuilt has recently leveraged new, innovative technology that streamlines the process and provides users with a more efficient experience. We can web-enable your permitting system, allowing resident, contractors, and homeowners to conveniently access permits, review statuses, and request inspections all online.

Applicant Notification Process

Applicants are notified, in writing, at the time of inspection by our inspection staff. Automatic email notification is being implemented at other operational villages as they upgrade their software. Inspectors are capable of resulting inspections in the field and can email applicants when email addresses are provided.

Tracking and Reporting Details

All SAFEbuilt inspections are tracked by permit number, type, and trade. Each trade inspector enters his or her own results into the reporting software at the time of inspection. Each inspector can attach external reports, pictures, or documents to the inspection.

Inspection reports from software systems can provide information about whether they failed, passed, or need re-inspection. Residential and commercial inspections are also tracked and compiled into a monthly report.

Details on Resources/Tools Available to Inspection Staff to Help Ensure that Time Frame, Quality Metrics, and Consistency are Met

As mentioned above, SAFEbuilt utilizes a routing software to help ensure that inspections are conducted efficiently and within the allotted time allowed. Inspection checklists and building guides are accessible from the inspector's iPads to assist with customers in the field. Electronic versions of the code books are also available on the iPad.

To ensure quality, SAFEbuilt has implemented a quality assurance program where our building officials and operations managers perform random quality inspection evaluations of our staff throughout the year. They also perform a ride-along with staff as a mentoring and training exercise. Additionally, SAFEbuilt conducts an annual training day, which includes all state personnel. Consistency is forged through our QA program and by training, as well as constant communication between all of our operations.

Professional Plan Review Services

At each SAFEbuilt office, we have trained our staff to issue permits, such as roofs, siding, flat work, fences, and a host of trade permits as "One Stop" permits, meaning it is issued at the time of application with all completed paperwork. SAFEbuilt aligns the comprehensive permit issuance process, including both internal and external agencies, with the Village's permit issuance goals.



Disciplines to be Reviewed

Building, Mechanical, Electrical, and Plumbing disciplines are reviewed for code compliance at all Illinois SAFEbuilt offices. We also have the capability to carry out fire alarm and suppression disciplines. Additionally, our team can conduct planning and zoning reviews, as well as civil and structural engineering reviews, at an additional fee on an as needed basis.

Details of Plan Review Process, including Coordination with Other Applicable City Departments, Zoning, and Intake Processes

Upon intake of the application and plans, SAFEbuilt will distribute to the appropriate contact provided by the client. A copy of the plan for review will be delivered (electronically or paper) to the appropriate contacts in Planning, Engineering, Fire, and any other

applicable departments when required by the permit type. SAFEbuilt will follow up on the status of reviews and will incorporate comments into one plan review in order to minimize correspondence. A full review of the plan will be completed so that only the comments sent out for correction need to be reviewed upon resubmittal. All reviews will be sent to the applicant electronically.

A pre-submittal meeting will convene when requested by the applicant, or our plans examiners feel it will result in a more seamless plan review process. SAFEbuilt will coordinate meetings to streamline the process. This includes bringing all stakeholders involved in the project to a meeting at Village Hall to go over plans.

A pre-construction meeting will convene when the contractor or building department staff feel it will contribute to a smooth start and ongoing building project. The process includes reviewing inspection requirements, testing, and special reporting requirements. SAFEbuilt will provide main points of contact for building department staff and contractor staff contact lists.

Tracking, Workflow, and Reporting Details

Tracking, workflow, and reporting details will be based on the Village's software capabilities. We will create an excel spreadsheet to track plan reviews by permit number and status. Outlook will be used to set reminders for deadlines for reviews.

If it is a one stop, it is issued at the time of submittal. If it is an item that needs to be reviewed, it is distributed by type. If it is a residential plan, it goes to the team member identified as responsible to conduct residential

reviews, and likewise with commercial requests. Once the plans examiner has validated the requirements have been met, our permit techs are advised. They will then prepare the permit card and contact the applicant to let them know when they can pick up their permit. Following these steps, the applicant pays the appropriate fee to the Village, and the permit is issued. By assigning a number at the time of intake, the permit can be tracked by number throughout the life of the project. Reports may be generated out of the permitting software at any of our listed operations. SAFEbuilt will provide a monthly report that includes the number of permits, plan reviews, inspections by type, certificates of occupancy, and project valuation.



Other Services Available to the Village

If the Village's permitting software cannot track and report on plan review timeliness, SAFEbuilt will utilize the Meritage tracking software. This helps to generate reports, as well as hold our plans examiners accountable to meet turnaround times. We are able to train our staff to use any electronic plan review that is currently being used by the Village. However, SAFEbuilt offers electronic submittal and plan review through ePlan and Blubeam Review if no service is currently available to the Village.

B. Qualifications

Corporate Organization

SAFEbuilt was founded in 1992 for the sole purpose of providing exceptional building department services to local government. Today, SAFEbuilt is one of the leading providers of community development department services in the country, partnering with over 300 communities of all shapes and sizes for the efficient delivery of privatized solutions. Our expertise includes, but is not limited to:

- ✓ Healthcare facilities
- ✓ Schools
- ✓ Resorts
- ✓ Prisons
- ✓ Retail and big-box stores
- ✓ Manufacturing plants
- ✓ Residential and retirement communities



SAFEbuilt has been expanding and continually improving municipal building departments for over 20 years. Our team currently manages municipality contracts with more than 300 full time employees. SAFEbuilt is established as a

professional firm with skilled staff and levels of management oversight to maintain a high degree of service delivery. We aim to help municipalities develop building ordinances, fee schedules, forms and permit issuances, inspections, and tracking/reporting processes.

Additionally, SAFEbuilt works to customize our service delivery to provide local governments with the services they need, in the manner in which their customers expect it. Our personalized approach provides proven best practices, personnel expertise, innovative technology, and improved service levels.

We understand that every public agency has a unique culture and specific requirements for their community improvement services. We work exclusively with public agencies to avoid any potential for conflict of interest. The quality and training of our staff, combined with our robust business systems and core commitment to the Village of Bensenville, ensure that you receive the highest levels of service, professionalism, and responsiveness in the industry.

Our employees are the best in the industry and a key reason for our success. In addition to the necessary technical skills, our hiring and training processes focus on ensuring our staff have the knowledge needed to work cooperatively with other internal Village departments, outside agencies, contractors, and citizens to make the process as efficient and customer-friendly as possible. It has taken years to develop and refine our business

practices to ensure that we staff our organizations with individuals who possess a unique balance of technical experience and customer service skills.

The SAFEbuilt team stands apart from others by remaining dedicated to a client centered philosophy that is based on our core values, which are:

- ✓ **Integrity** – We choose to do the right thing every time.
- ✓ **Improvement** – We strive to continuously improve and understand how we can do better tomorrow.
- ✓ **Service** – We always provide unequaled service levels to our customers, external and internal.
- ✓ **Teamwork** – We have an environment where everyone is able to contribute ideas. We encourage and reward creativity and initiative.
- ✓ **Respect** – We are respectful in the way we interact with everyone.

Whether your community is facing unpredictable growth, a shortage of certified staff, a fluctuating workload, or a large and unique project, SAFEbuilt can make a difference where you need it.



Recent Experience with Similar Projects

SAFEbuilt provides services of similar scope, size, and complexity to over 300 clients. Of those contracts, the following Illinois examples highlight our capabilities to perform the requirements for Bensenville.

- ✓ **Village of Wilmette**
 - Plan Review
 - Inspections
- ✓ **Village of Glenview**
 - Plan Review
 - Inspections
 - Permit Technician
 - Code Enforcement
- ✓ **Village of Winnetka**
 - Plan Review
 - Inspections
- ✓ **City of Evanston**
 - Plan Review
 - Inspections
- ✓ **Village of Downers Grove**
 - Inspections
 - Code Enforcement
- ✓ **Village of Itasca**
 - Plan Review
 - Inspections
 - Building Code Update

Transition Experience

We refer to the time from contract completion to our service start date as the transition period. Upon approval at the 10/27/15 Board Meeting, SAFEbuilt will be ready to go live 11/02/15 in Bensenville. We anticipate a very short transition period and will work with Bensenville to make it as seamless as possible. Over the years we have honed our process for addressing concerns and implementing successful programs for jurisdictions across the country. We have found that the keys to success include having the right team involved; getting the appropriate stakeholders involved in the process; understanding current systems, processes, and interactions; and communicating effectively throughout the process. While each transition has its unique characteristics, our experience will help guide you through the process.

Experienced Team

SAFEbuilt has assembled a team of professionals with the experience, skills, and tools necessary to establish a program for Bensenville that will meet your needs and achieve your goals. They have direct experience working for Village governments and have expertise in the use of technology, process flow, customer service, and the technical aspects of operating a building department. Most importantly, they have worked on transitions for other clients and know what it takes to do this well. This team will be there to support your community during the transition period and remain available until you are satisfied the transition is complete.

Customized Process

Your transition team and our process will provide the guidelines for the transition; however, we know that what worked well in Glenview, for example, may not be as effective in Bensenville. The details of each transition come from you and your stakeholders. We work hard to ensure the right people are involved in the process from the start. The perspectives of the developer will be different than that of the Planning Department and it is important to consider all these perspectives. We are also not interested in making wholesale changes. What works well

Ensuring a Successful Transition

- ✓ While you may have questions about the transition process, we have the experience necessary and the tools in place to take much of the uncertainty out of the equation.
- ✓ Our team knows your challenges and have learned to adapt to necessary changes. Your stakeholders will be involved in the process from the start and your best processes will be maintained and incorporated.
- ✓ We will communicate with one another throughout the process to ensure we are on the right track and ensure everyone is aware of the changes ahead.

today? What would you like to see improved going forward? Those are equally important questions and the transition team will seek out those answers.

Part of seeking those answers involves reviewing the current processes in place. We will look at what data is being collected today and how it is collected. We will gain an understanding of the current process flow between departments and between jurisdictions. We will also review the web-based and printed resources available to everyone. This analysis will allow us to customize your program to meet your needs and operate as efficiently as possible.

Our goal is to become an extension of your staff and a part of the overall team. We will schedule regular check-ins to measure progress and gauge satisfaction.

Effective Communication

We have also found that one of the keys to success throughout the process is effective communication. It is important that everyone involved be aware of progress and changes they can expect going forward. Face-to-face meetings are an integral part of the plan and will involve all key stakeholders at various points in the process. We will prepare communications that are sharable with all Village staff about what to expect. We will provide an open-house for builders, staff, and even residents to come and hear about our progress. We will also work with you to determine what other efforts should be taken to make sure the right information is getting to the right people. Throughout the process, you can expect to see updates on the progress of the transition team and any changes to the overall schedule. This fills everyone with confidence that the process is on track and that their voices are heard. It is our priority to ensure a successful transition with minimum impact on Bensenville and its citizens.

The SAFEbuilt Illinois Team

Steve Touloumis – Regional Chief Building Official

Steve is a certified Building Code Official and has provided code compliant building department services since 1999. In addition to his municipal government experience providing building official, plan review, inspection and administrative services, Steve has worked in the construction industry as a Master Electrician.

ICC Certifications

- ✓ Master Code Professional
- ✓ Certified Building Official
- ✓ Combination Plans Examiner
- ✓ Commercial Building Inspector
- ✓ Commercial Electrical Inspector
- ✓ Commercial Mechanical Inspector
- ✓ Commercial Plumbing Inspector
- ✓ Residential Plans Examiner
- ✓ Residential Energy Inspector/Plans Examiner
- ✓ Residential Building Inspector
- ✓ Residential Electrical Inspector
- ✓ Accessibility Inspector/Plans Examiner

Work Experience

- ✓ Building Official – SAFEbuilt, IL 2014 to Present
- ✓ Chief Building Inspector – Oak Park, IL 2006 to 2014
- ✓ Code Compliance Officer – Oak Park, IL 2003 to 2006
- ✓ Building Inspector/Electrical – Oak Park, IL 1999 to 2003

Kenneth Bauer – Deputy Building Official

Ken has experience providing code compliant building department services to municipal government that include administration, plan review and inspection. Additionally, Ken is a trained FEMA Disaster Inspector and Home Inspector in the State of Illinois.

International Code Council Certifications:

- ✓ Master Code Professional
- ✓ Certified Building Code Official
- ✓ Certified Electrical Code Official
- ✓ Certified Plumbing Code Official
- ✓ Certified Mechanical Code Official
- ✓ Certified Building Official
- ✓ Building Inspector
- ✓ Combination Inspector
- ✓ Electrical Inspector
- ✓ Mechanical Inspector
- ✓ Building Plans Examiner
- ✓ Combination Plans Examiner
- ✓ Electrical Plans Examiner
- ✓ Plumbing Plans Examiner
- ✓ Mechanical Plans Examiner
- ✓ Commercial Building Inspector
- ✓ Commercial Combination Inspector
- ✓ Commercial Electrical Inspector
- ✓ Commercial Plumbing Inspector
- ✓ Commercial Mechanical Inspector
- ✓ Residential Building Inspector
- ✓ Residential Combination Inspector
- ✓ Residential Electrical Inspector
- ✓ Residential Mechanical Inspector
- ✓ Residential Energy Inspector
- ✓ Property Maintenance & Housing Inspector
- ✓ Accessibility Inspector/Plans Examiner

Kenneth Bauer – Deputy Building Official (Continued)

Professional Memberships:

- ✓ Illinois Fire Service Institute

Professional Experience:

- | | |
|--|-----------------|
| ✓ Deputy Building Official – SAFEbuilt | 2014 to Present |
| ✓ Plans Examiner – Oak Park, IL | 2008 to 2014 |
| ✓ Building Inspector – Sugar Grove, IL | 2005 to 2008 |

David Weide – Building Inspector/Plans Examiner

David has over 20 years of experience as a building inspector, plans examiner, and building official. He has been responsible for the day to day operations of numerous departments including supervising staff, handling complaints, writing code and ordinances, issuing citations, and preparing budgets. His background includes experience as a journeyman carpenter, foreman, and construction superintendent and retains extensive knowledge in building construction including the associated trades, (i.e. plumbing, electrical, and mechanical). As a firefighter/paramedic, David has performed fire inspections checking for fire code and housekeeping violations.

ICC Certifications:

- | | |
|------------------------------------|----------------------------------|
| ✓ Building Official | ✓ Building Code Official |
| ✓ Building Plans Examiner | ✓ Building Inspector |
| ✓ Residential Building Inspector | ✓ Commercial Building Inspector |
| ✓ Residential Mechanical Inspector | ✓ Residential Plumbing Inspector |
| ✓ Housing Code Official | ✓ Property Maintenance Inspector |

Illinois State Board of Education License:

- | | |
|-------------------------------|---------------------------|
| ✓ Building Code Plan Reviewer | ✓ Building Code Inspector |
|-------------------------------|---------------------------|

Professional Affiliations

- ✓ International Code Council

Work Experience

- | | |
|--|-----------------|
| ✓ Building Inspector/Plans Examiner – SAFEbuilt Illinois | 2013 to Present |
| ✓ Building Official – Oskaloosa, IL | 2013 to 2014 |
| ✓ Assistant Building Division Manager – Lake Zurich, IL | 2006 to 2013 |
| ✓ Building/Zoning Official – East Dundee, IL | 2004 to 2005 |
| ✓ Senior Inspector/Plans Examiner – Des Plaines, IL | 2001 to 2004 |
| ✓ Journeyman Carpenter – Various Companies | 1971 to 2001 |
| ✓ Firefighter/Paramedic – Palatine, IL | 1975 to 1995 |

Frank Sygulla –Building Inspector / Code Enforcement Officer

Frank has 16 years of experience providing code enforcement services within the State of Illinois. In addition to his code enforcement experience Frank has worked as a licensed fee appraiser and real estate specialist.

ICC Certifications: #5170595

- | | |
|------------------------------------|--|
| ✓ Building Inspector | ✓ Commercial Building Inspector |
| ✓ Residential Building Inspector | ✓ Property Maintenance and Housing Inspector |
| ✓ Fire Inspector I | ✓ Zoning Inspector |
| ✓ Residential Mechanical Inspector | ✓ Residential Electrical Inspector |

Professional Affiliations

- ✓ International Code Council
- ✓ Economic Development Committee for the Sustainability Master Plan Advisory
- ✓ Golden Key International Society

Work Experience

- | | |
|---|-----------------|
| ✓ Inspector / Code Enforcement Officer – SAFEbuilt | 2013 to Present |
| ✓ Commercial Real Estate Specialist – Robert Half Legal, IL | 2012 to 2013 |
| ✓ Senior Code Enforcement Officer – Elgin, IL | 1995 to 2010 |

David DeLeon – Building Inspector / Code Enforcement Officer

David is one of our Building Inspectors and Code Enforcement Officers. Prior to joining the SAFEbuilt team in 2013, David was a Seasonal Inspector for the City of Aurora, IL for three years.

ICC Certifications:

- | | |
|------------------------------------|--|
| ✓ Residential Building Inspector | ✓ Residential Electrical Inspector |
| ✓ Residential Mechanical Inspector | ✓ Property Maintenance and Housing Inspector |

Professional Affiliations

- ✓ International Code Council

Work Experience

- | | |
|--|-----------------|
| ✓ Inspector / Code Enforcement Officer – SAFEbuilt | 2013 to Present |
| ✓ Sales Associate – UPS Store | 2005 to 2013 |
| ✓ Seasonal Inspector / Worker II – Aurora, IL | 2005 to 2008 |

Raymond “Ray” Helmer – Plans Examiner/Building Inspector

Before joining the SAFEbuilt team, Ray provided commercial plan review services for a private firm in Elkhart, Indiana. Additionally, Ray has more than 20 years’ experience in project management, is skilled in dealing with the public, and understands the importance of customer service.

ICC Certifications:

- | | |
|--------------------------------------|---|
| ✓ Master Code Professional | ✓ Certified Building Code Official |
| ✓ Certified Housing Code Official | ✓ Certified Electrical Code Official |
| ✓ Certified Mechanical Code Official | ✓ Certified Plumbing Code Official |
| ✓ Certified Building Official | ✓ Combination Plans Examiner |
| ✓ Commercial Energy Inspector | ✓ ICC/AACE Property Maintenance & Housing Inspector |
| ✓ Residential Combination Inspector | ✓ Residential Energy Inspector/Plans Examiner |

Professional Affiliations

- ✓ International Code Council

Professional Experience:

- | | |
|--|-----------------|
| ✓ Plans Examiner – SAFEbuilt | 2014 to Present |
| ✓ Plans Examiner/Inspection Auditor – TR Arnold & Associates | 1994 to 2014 |

James (Jim) Kemper – Plumbing Inspector

Jim is a certified Plumbing inspector with over 15 years of experience as a Journeyman Plumber. Prior to joining SAFEbuilt in 2014, Jim provided services to numerous communities in Illinois.

ICC Certifications

- ✓ Plumbing Inspector

Illinois State Certifications

- ✓ City of Chicago Journeyman Plumber

Professional Affiliations

- ✓ International Code Council

Recent Work Experience

- | | |
|---|-----------------|
| ✓ Plumbing Inspector – SAFEbuilt, IL | 2014 to Present |
| ✓ Plumbing Inspector – TPI Building Code Consultants | 2011 to 2014 |
| ✓ Business Agent – Present Primerica Financial Services | 2009 to Present |
| ✓ Journeyman Plumber – Corporate Plumbing, Inc. | 2008 to 2009 |
| ✓ Journeyman Plumber – Werner Nugent Plumbing Company | 2007 to 2008 |
| ✓ Journeyman Plumber – AM Mechanical, Inc. | 2006 to 2007 |
| ✓ Journeyman Plumber – Epic Plumbing and Mechanical | 2004 to 2006 |
| ✓ Journeyman Plumber – Wheeling Plumbing Company | 1998 to 2004 |

Robert “Bob” Richardson – Plumbing Inspector

Bob has over 29 years of experience providing professional plumbing inspections and installation as a Journeyman Plumber. He is experienced in all aspects of residential, commercial, and industrial plumbing.

State of Illinois Licenses:

- ✓ IDPH Certified Plumbing Inspector
- ✓ Journeyman Plumbers License

Professional Memberships:

- ✓ Plumbing and Pipe Fitting Trade School

Professional Experience:

- ✓ SAFEbuilt – Plumbing Inspector - 2013 to present
- ✓ Ewing-Doherty Mechanical, Bensenville, IL – Foreman/Journeyman Plumber – 1985 – 2012

Richard “Rich” Irsay – Plumbing Inspector

Rich gained experience providing municipal plumbing inspections for the Village of East Dundee and the Village of Wheeling. He is also a State of Illinois licensed plumbing inspector.

State of Illinois Licenses:

- ✓ IDPH Certified Plumbing Inspector
- ✓ Plumbing Inspector-#J14686
- ✓ Journeyman Plumbers License

Professional Experience:

- ✓ SAFEbuilt – Plumbing Inspector - 2013 to present
- ✓ Village of East Dundee – Plumbing Inspector – 2012 – 2013
- ✓ Village of Wheeling – Plumbing Inspector – 2006 to 2009
- ✓ Irsay Plumbing & Mechanical – Owner/Operator – 1993 to present

Recent Firm Experience in Surrounding Areas near Bensenville

Please see “Recent Experience with Similar Projects” in Section B (Qualifications, page 9) for a list of our current projects in surrounding areas near Bensenville.

C. Schedule

Each of the requested services involves certain deliverables that form the basis for our performance metrics and will guide our ongoing and continuous improvement efforts. Reaching agreement on performance metrics is part of the transition process. However, we have listed a number of service levels and metrics that you and your stakeholders can expect to see.

Deliverable	Detail	Benefit to Bensenville
NEXT-DAY INSPECTIONS	We will perform 100% of all inspections called in by 4:30pm the next business day.	This gives contractors confidence that their projects can remain on schedule and is reported against regularly.
MOBILE RESULTING	We provide our inspectors with field devices to enter results immediately.	This dramatically increases productivity by providing immediate access to information.
PRE-SUBMITTAL MEETINGS	We offer pre-submittal meetings to applicants.	This is a great tool to get projects kicked off properly and saves time and effort further down the process.
PLAN REVIEW TURNAROUND TIMES	We will meet our commitment on plan review turn-around times 100% of the time. We will provide first comments on residential projects within 5 business days and second comments within 3 business days. For multi-family projects, we will provide first comments within 10 days and second comments within 5 days. For small commercial projects (under \$2M in valuation), our team will provide first comments within 10 days and second comments within 5 days. Finally, for large commercial projects (over \$2 million), we will provide first comments within 15 working days and second comments within 10 business days.	Meeting these deadlines will require cooperation with other departments and agencies, but is integral to keeping applicants happy and their schedules on track. We regularly report against this metric.
APPLICANT SATISFACTION	We will put a survey in place that allows applicants to provide feedback on their experience throughout the process.	This not only provides an outlet for citizens to voice their opinions but it also provides excellent insight into what is working well and what we can do better going forward. We will report on the results of this feedback regularly.

Reporting

We will work with Bensenville to develop a reporting schedule and format that meets your needs. We can provide monthly, quarterly, and annual reports summarizing activity levels; adherence to our performance metrics; and other items that are of special interest to you.

D. Costs

We will be providing services to Bensenville according to the specifications, terms, conditions, and instructions listed below.

The fees will apply as follows:

Table A:

	Over the Counter	Accessory or Alteration	Addition	New Construction
Single Family Residential				
Plan Review	N/A	\$23.62	< 500 sqft \$328.12 > 500 sqft \$415.62	\$525.00
Inspection (Each)	\$35.00	\$35.00	\$35.00	\$35.00
Re-Inspection (Each)	\$35.00	\$35.00	\$35.00	\$35.00
Multiple Family Residential				
Plan Review	N/A	\$23.62	See Table B	N/A
Inspection (Each)	\$43.75	\$43.75	\$43.75	\$43.75
Re-Inspection (Each)	\$43.75	\$43.75	\$43.75	\$43.75
Non-Residential				
Plan Review	\$23.62	See Table B	See Table B	See Table B
Inspection (Each)	\$43.75	\$43.75	\$43.75	\$43.75
Re-Inspection (Each)	\$43.75	\$43.75	\$43.75	\$43.75

Table B: Commercial & Multiple Family Plan Reviews

Gross Floor Area (sqft)	Base Building	Base Building + (2) Disciplines	Base Building + (3) Disciplines
0 to 2500	\$455.00	\$549.50	\$752.50
2501 to 4000	\$507.50	\$686.87	\$923.12
4001 to 5000	\$712.00	\$928.00	\$1,220.00
5001 to 7500	\$806.40	\$1,129.60	\$1,400.00
7501 to 10,000	\$888.00	\$1,176.00	\$1,580.00
10,001+	\$976.00	\$1,464.00	\$1,948.80
Each 1000 sqft over 10,000	\$20.00	\$28.00	\$40.00

Fee Notes:

- ✓ Plan review fee covers all necessary plan submittals at no additional charge
- ✓ All re-inspections will be charged against the permit escrow. In the event the cost of re-inspection exceeds the available escrow, the applicant will need to submit a second escrow to cover the re-inspection fees.

Contract Terms

- ✓ We generally request a one year agreement for this model of services – we can provide the draft agreement or it can come from your attorney
- ✓ Billing will come monthly with all supporting documentation
- ✓ Billing terms are Net 30

Insurance

SAFEbuilt carries the full complement of business insurance including errors and omissions (E&O), property, liability, auto, and workers compensation. Certificates of insurance in the following amounts that name the Village of Bensenville as additional insured will be provided.

General Liability:	✓ Each Occurrence - \$1,000,000
	✓ Damage to Rented Premises Each Occurrence - \$1,000,000
	✓ Personal Injury Each Occurrence - \$1,000,000
	✓ General Aggregate - \$2,000,000
Automobile Liability:	✓ Each Occurrence - \$1,000,000
Umbrella Liability:	✓ Each Occurrence - \$5,000,000
	✓ Aggregate - \$5,000,000
Professional Liability:	✓ Per Claim - \$5,000,000
Workers Compensation:	✓ Per State requirements

Community Outreach Programs

SAFEbuilt is more than just a community's building department. We strive to provide a higher level of professionalism, expertise, and service than that of a typical department. In line with this belief, SAFEbuilt has developed several professional and community outreach programs designed to help the community through education, outreach, and charitable giving. We want to be involved in every community we represent, and we would like our partner communities to understand that SAFEbuilt is here not just as a building department, but also as a contributing member of the community. The following are just a few examples of what SAFEbuilt can do for Bensenville:

Community Events

SAFEbuilt can sponsor or volunteer for community events like a Fourth of July celebration or a concert series. Events may mark the opening of a recent project or celebrate a recent recognition of the city or town. In each of these cases, SAFEbuilt sets aside volunteer time so that our staff can assist with the event and/or an amount of money to donate to the city to alleviate costs.



Volunteer Time

SAFEbuilt will donate "time" to Bensenville. By volunteering at local non-profits, we contribute to the betterment of the city and consider volunteer work to be essential in realizing the goals set forth by leadership. Programs may include art councils, animal shelters, recreation programs, Habitat for Humanity, etc.

Open House

We work with our clients to promote teamwork with city officials. SAFEbuilt usually hosts one open house a year. Goals include:

- ✓ Provide an informal atmosphere to promote open discussion between the community and SAFEbuilt.
- ✓ Promote the experience and expertise of the staff with displays or handouts featuring certifications or special projects completed.
- ✓ Common expenses covered by SAFEbuilt include refreshments (meals, snacks, beverages, etc.), invitations, and brochures to promote the event.

Homeowners Workshops

Workshops are a great way to connect with the citizens of the community and general contractors. These clinics focus on helping the homeowner understand how to correctly manage a construction project such as building a deck or finishing a basement.

Why SAFEbuilt?

Throughout this proposal, our aim was to demonstrate our capabilities to meet the goals of the Village of Bensenville. Below is a brief follow-up of the benefits you will receive by choosing SAFEbuilt for your Building Department Services.

- ✓ Bensenville will gain the advantages of utilizing SAFEbuilt's experience in providing a smooth transition of services
- ✓ SAFEbuilt ensures you have a professionally managed department while we customize services to meet the changing needs of the Village and stakeholders
- ✓ Our team eliminates the concern regarding staffing issues for contracted services in response to fluctuations in activity.



...MAINTAIN CONTROL OF THE DEVELOPMENT PROCESS



...INCREASE LEVEL OF SATISFACTION FOR APPLICANTS AND CITIZENS



...WORK IN AN ENVIRONMENT OF COOPERATION



...BE ENSURED THAT DELIVERABLES ARE MET



...STAY INFORMED WITH REGULAR REPORTING



...BE CONFIDENT THAT LIFE SAFETY IS A PRIORITY



...BE ABLE TO EFFECTIVELY MANAGE THE EXTREME FLUCTUATION IN ACTIVITY



...GAIN A PARTNER THAT WILL PARTICIPATE AND GIVE BACK TO THE COMMUNITY

E. References

In addition to the references listed below, please feel free to contact any of our current clients. A complete list of our building department services clients follows the highlighted list below.

Village of Glenview, Illinois

Joe Kenney, Community Development Director
1225 Waukegan Road, Glenview, IL 60025
Phone: 847.904.7340
Email: joek@glenview.il.us

City of Evanston, Illinois

Maleka Sumar, Manager Analyst Community Development
2100 Ridge Avenue, Evanston, IL 60201
Phone: 847.866.2925
Email: msumar@cityofevanston.org

Village of Winnetka, Illinois

Michael D'Onofrio, Director of Community Development
510 Green Bay Road, First Floor, Winnetka, IL 60093
Phone: 847.716.3526
Email: md'onofrio@winnetka.org

Village of Downers Grove, Illinois

Stan Popovich, Planning Manager
801 Burlington Ave., Downers Grove, IL 60515
Phone: 630.434.5500
Email: spopovich@downers.us

Village of Itasca, Illinois

Nancy Hill, Community Development Director
550 W Irving Park Road, Itasca, IL 60143
Phone: 630.773.5568
Email: nhill@itasca.com

Client List

For over twenty years, our sole focus and commitment has been to local governments, providing complete building department administration, plan review, inspection, community planning and zoning, property maintenance, code enforcement, and more. SAFEbuilt has a deep understanding of the challenges local governments face on a daily basis. This has allowed us to develop the systems, processes, and culture needed to partner with and effectively serve a wide variety of communities. Below is a partial list of our current clients.

Aims Community College, CO	Colorado State University	Glenview, IL
Abbeville County, SC	Colorado, State of	Grand Blanc, MI
Almont, MI	Commerce City, CO	Goodrich, MI
Andrews, SC	Dacono, City	Grand Haven Township, MI
Antwerp Township, MI	Danby Township, MI	Grayling, MI
Aspen, CO	Dearborn, MI	Grayslake, IL
Ault, CO	Decatur, GA	Green Oaks, IL
Aurora, IL	Dekalb, IL	Greenwood, SC
Avon, CO	Delta Charter Township, MI	Grosse Ile Township, MI
Baldwin County, GA	Denver, CO	Grover, CO
Bargersville, IN	DeWitt, MI	Gypsum, CO
Barnwell, SC	Dorchester County, SC	Hampton, GA
Bay Village, OH	Downers Grove, IL	Hamtramck, MI
Beaufort, SC	Dundee Township, MI	Hapeville, GA
Beecher, IL	Eagle, CO	Harper Woods, MI
Bennett, CO	Easley, SC	Hart, MI
Berea, OH	East Grand Rapids, MI	Hayden, CO
Bertrand Township, MI	Edgewater, CO	Hudson, CO
Beverly Hills, MI	Elbert County, CO	Idaho Springs, CO
Birmingham, MI	Elizabeth, CO	Imlay City, MI
Bloomfield Hills, MI	Evanston, IL	Independence Township, MI
Bluffton, SC	Exeter Township, MI	Itasca, IL
Breckenridge, CO	Farmington, MI	Ivinson Memorial Hospital, WY
Bridgeton Township, MI	Ferndale, MI	Jasper County, SC
Brighton Township, MI	Ferrysburg, MI	Johns Creek, GA
Bull Valley, IL	Firestone, CO	Jonesboro, GA
Butts County, GA	Fowlerville, MI	Keenesburg, CO
Byron Township, MI	Foxfield, CO	Kersey, CO
Cannon Township, MI	Franklin, TN	Kiawah Island, SC
Castle Pines, CO	Fremont, MI	Kiowa, CO
Centennial, CO	Frisco, CO	Lake Bluff, IL
Chamblee, GA	Genoa Township, MI	Lake City, GA
Chattahoochee Hills, GA	Georgetown, CO	Lake County, CO
Chester, SC	Georgetown, SC	Lake in the Hills, IL
Colorado Division of Housing	Gilcrest, CO	Lamar, CO

Lansing, MI	Northlake, IL	Sherman Township, MI
Laramie County, WY	Norton Shores, MI	South Carolina, State of
Lasalle County, IL	Nunn, CO	South Lyon, MI
Lily Lake, IL	Oak Park, MI	St. John's Medical Center, WY
Lincoln Park, MI	Ohio HRPC	Stone Mountain, GA
Lithonia, GA	Olmsted Falls, OH	Sullivan Township, MI
Lochbuie, CO	Orangeburg, SC	Summerton, SC
Longmont, CO	Parachute, CO	Suttons Bay, MI
Lyons, CO	Peachtree City, GA	Tallmadge Township, MI
Macomb, MI	Pentwater, MI	Thornton, CO
Madison Heights, MI	Peotone, IL	Timberlane, IL
Marlboro County, SC	Pierce, CO	Timnath, CO
Marseilles, IL	Pine Lake, GA	Troy, MI
Maybee, MI	Pitkin County, CO	Tyrone, GA
Mead, CO	Platteville, CO	Union City, GA
Meeker, CO	Port Royal, SC	University of Northern Colorado
Michigan MDEQ	Powder Springs	Vail, CO
Michigan MDOT	Putnam Township, MI	Volo, IL
Michigan MEDC	Raisinville Township, MI	Waterman, IL
Milton, GA	Red Cliff, CO	Weesaw Township, MI
Minturn, CO	Richmond Hill, GA	Weld County School District, CO
Morrison, CO	Robinson Township, MI	Wellington, CO
Morrow, GA	Romulus, MI	Williamsburg County, SC
Mount Pleasant, SC	Rose Township, MI	Wilmette, IL
Mountain Park, GA	Roswell, GA	Windsor, CO
Mountain View, CO	Saluda, SC	Winnetka, IL
Muskegon Heights, MI	Sauk Village, IL	Wixom, MI
Muskegon, MI	Senoia, GA	Wonder Lake, IL
Nederland, CO	Severance, CO	Ypsilanti Charter Township, MI
Newberry County, SC	Sharpsburg, GA	Zeeland, MI
Northglenn, CO	Shelby Township, MI	

F. Sample Work

Please see the following samples of Building Code, Inspections, and Plan Review examples for your review.

- ✓ Building Code Review (1)
- ✓ Building Code Review (2)
- ✓ Inspection
- ✓ Plumbing Inspection
- ✓ Plan Review



Plan Review 1	Building Code Review / Response Meadow Park Outpatient	Building Code Reviewer: Ray Helmer SAFEbuilt
--------------------------------	---	---

Building Code Review Status		
Review 1:	Insert date: January 26, 2015	Not Approved
	Dwgs. Dated: January 12, 2015	
Review 2:		

Resubmittal Instructions:

- ① Return this sheet with 4 sets of the revised drawings/documents to the Permit Desk, Development & Planning Services, on the 2nd Floor of the Village Hall.
- ① On this sheet, complete the Revision Location & Response boxes! The design professional of record must indicate the location of each revision & respond to every comment in the spaces provided.
- ① Identify all drawing revisions with a bubble.
- ① Any revisions that are in addition to the review comments must be bubbled and explained in the separate letter.

Building Code Review Comments

- B1 Vestibule 184 - Doors in series are not positioned for Accessible use. Provide additional space allowance for this purpose. IBC Section 1008.1.8.

Revision Location	Response

- B2 Toilet room # 167 -The Lavatory is in an alcove that has not been dimensioned for Accessible approach. Indicate the required 36" clear width required by the ANSI Standard.

Revision Location	Response:

- B3 Complete and verify the Code information on the Cover Sheet.

Revision Location	Response:

- B4 Complete and verify the Code Summary on Sheet LS1-1.

Revision Location	Response:

- B5 On Sheet LS1 (or elsewhere) show Egress travel distances, Occupant Loads, actual and allowable elemental Egress dimensions and widths. Show the Common Path of Travel distances.

Revision Location	Response:

- B6 The proposed work is considered an Alteration of an existing structure. Provide an Energy Envelope Compliance Report for this type of construction effort, using COMCHECK or equivalent approvable method.

Revision Location	Response:

- B7 Also include a Lighting and Mechanical compliance report.

Revision Location	Response:

- B8 According to Specification Section 1010.1.2.E, and the project submittal drawings, this project is a tenant build out within an existing wood framed, non-fire protected structure. Provide tabular compliance data from the requirements in IBC Chapters 5 and 6 for the allowable height and area and Fire Separation Distances for this structure.

Revision Location	Response:

- B9 Provide data and/or information that will verify that the existing structure is compliant with all new structural loadings, both Live and Dead that will be imposed on it due to the new Occupancy. IBC Section 1603.1.

Revision Location	Response:

- B10 Provide data and/or information that the proposed occupancy is to be used as an Occupancy Category II structure and need not be considered Occupancy Category IV according to IBC Section T 1604.5.

Revision Location	Response:

- B11 Provide information on the proposed occupancy showing compliance with requirements for the area of the Exterior Wall openings, based on the Fire Separation Distance. IBC Section T 705.8.

Revision Location	Response:

- B12 Indicate on the Plan Cover Sheet that the proposed Occupancy is not going to be used as an "Ambulatory Health Care Facility". If this is not the case, then this review must be considered preliminary and an additional review for smoke issues must be done.

Revision Location	Response:

- B13 A door hardware specification for the various doors is not found in the plan set or the Specifications. Various compliance issues therefore cannot be verified.

Revision Location	Response:

- B14 NFPA 101 - Life Safety Code - Reduces Exit Access Travel Distance for this type of Occupancy compared to the International Building Code. Combine this into the compliance comparison for item B5 above.

Revision Location	Response:

- B15** From NFPA 101 - Provide data/information that will permit this Occupancy not to have an NFPA 99 "Essential Electrical System"

Revision Location	Response:

- B16** Floor proximity Exit Signs are also required by section 7.10.1.6 of NFPA 101.

Revision Location	Response:

- B17** The Mechanical drawings do not show return air ducts. Provide specifications for construction materials that are not permitted within plenums. M 602.2.1.

Revision Location	

- B18** Provide information on the Fire Suppression system being extended into the trussed roof area in order to eliminate the need for Draft Stopping. IBC 717.4.

Revision Location	Response:

- B19** There is no plan indication of emergency lighting provisions in the Electrical Room. There is the same requirement for the Sprinkler Room, although one is not found on Sheet LS1-1. Municipal Amendment to NEC Section 110.26(D)(1).

Revision Location	Response:

- B20** An attic access is required for the assumed trussed configuration. Section 1209.2. This space must be lighted in accordance to the Municipal Amendments to NEC Section 210.70(A) (3).

Revision Location	Response:

Responder to complete this box:

Revisions prepared & submitted by: _____ Print Name Title or Company Name	Date: _____
--	--------------------

End of Building Code Review



**Plan Review
1**

Building Code Review / Response
501 Lindberg Drive
Bell Flavors breakroom/mezzanine

Building Code Reviewer:
Steve Touloumis
SAFEbuilt

Building Code Review Status

Review 1:	9/3/14	Not Approved
	Dwgs. Dated:	8/14/14
Review 2:		
	Dwgs Dated:	

Resubmittal Instructions:

- ① Return this sheet with 4 sets of the revised drawings/documents to the Permit Desk, Development & Planning Services, on the 2nd Floor of the Village Hall.
- ① On this sheet, complete the Revision Location & Response boxes! The design professional of record **must** indicate the location of each revision & respond to every comment in the spaces provided.
- ① Identify all drawing revisions with a bubble.
- ① Any revisions that are in addition to the review comments must be bubbled and explained in the separate letter.

Building Code Review Comments

- B1 Add the 2000 Life Safety Code to list of applicable codes. Verify design is compliant with the Life Safety Code.

Revision Location	Response:

- B2 List the Subclassification per the Life Safety Code, section 40.1.4.1

Revision Location	Response:

- B3 Show the shelving floor plan and height in the mezzanine storage area and show the exit travel distance from the mezzanine. Verify that the distance is compliant.

Revision Location	Response:

- B4 Welds shall be inspected by a special inspector per Chapter 17 of the IBC—note the requirement for this on the plans.

Revision Location	Response:

- B5 Sinks shall comply with the Illinois Accessibility Code. Provide dimensions and details on plans showing compliance.

Revision Location	Response:

- B6 Electrical load calculations shall be provided for the panels that load is being added to, any intermediate feeders that supply these panels, and the building service(s). This includes the standard power and lighting, as well as the RTU. Field determination is not acceptable.

Revision Location	Response:

Page 1 of 2

--	--

- B7 Page PP6-00-01 notes to connect the DCW & DHW to the existing san and vent piping. Correct this note.

Revision Location	Response:

- B8 Provide an explanation of 'Future Confection'. Water supplies lines cannot dead-end more than two feet; explain/show how this won't occur with the 'future' lines connected to the supply distribution system. Note--Shut off valves are not acceptable to isolate the lines while waiting for the future fixtures to be added.

Revision Location	Response:

B9

Revision Location	Response:

B10

Revision Location	Response:

B11

Revision Location	Response:

B12

Revision Location	Response:

Responder to complete this box:

Revisions prepared & submitted by: _____	Date: _____
Print Name	Title or Company Name

End of Building Code Review

Printed by John Norman

INSPECTION FIELD SHEET

07/09/15
15:29:43

INSPECTION: 206348 BASE STEPS

PERMIT: 83245
STATUS: ISSUED 04/24/15
APPLICATION: 201500180

LOC: 406 PRAIRIE
WILMETTE

PROPERTY ID: 05341150200000

OWNER: MARTA DROZOWICZ
773-677-1771
CONTRACTOR: CAREW, ROGER

REQUEST BY: LOUISE *LOUISE ON SITE*
262-620-5973

PROJ DESC: NEW SINGLE FAMILY HOME
WORK ORDER:

INSPECTOR: ST
REQUESTED: 07/09/15
SCHEDULED: 07/10/15 AM
UNPAID FEES: .00

RESULT: *NOT APPROVED*
PRIORITY:
COMPLETED: *7/10/15 10:45am*
Date Time

MILEAGE: TIME: TRAVEL ONSITE

COMMENTS:

FRONT, SIDE AND REAR STOPS.
① PLANS ON SITE DO NOT APPEAR TO BE APPROVED BY VILLAGE, THE PLANS ON SITE ARE FOR 921 OAKWOOD, WILMETTE, WHICH HAS BEEN SCRATCHED OUT AND 406 PRAIRIE WRITTEN ON THE PLAN SET. FRONT PAGE SHOWS 406 PRAIRIE.

ALL INSPECTIONS:

INSPECTED	INSPECTOR	RESULT	INSP	DESCRIPTION
	JN		B010	BASE - DRIVEWAY
	JN		B020	BASE - PATIO
05/14/15	JN	PASSED	B025	FOOTING
				REBAR IN PLACE AND PUMP ON SITE FOR WATER IN FOOTING
	JN		B030	TRENCH
	JN		B035	PIERS
05/20/15	JN	PASSED	B040	FOUNDATION
				WALLS BRACED WITH REBAR TIED IN PLACE
	JN	FAILED	B045	BASEMENT FLOOR
06/02/15	JN	PASSED	B046	REINSPECT BASEMENT FLOOR
06/03/15	JN	PASSED	B050	GARAGE FLOOR/SLAB
07/07/15	JN	PASSED	B067	BUILDING WRAPS
			B068	WINDOWS AND DOORS
05/28/15	JN	PASSED		
05/28/15	JN	PASSED		

REAR STOPS

② PLANS DO NOT SHOW DETAIL FOR THE STOPS. PARTICULARLY FRONT PORCH HAS COLUMNS, DO THE COLUMNS NEED MIN. 42" DEEP COLUMNS?
③ LAYOUT FOR FRONT PORCH DOES NOT MATCH ELEVATION.

pm

Printed by John Norman

INSPECTION FIELD SHEET

07/09/15
15:29:43

INSPECTION: 209966

CONSTRUCTION FINAL

PERMIT: 83912

STATUS: ISSUED 06/01/15

APPLICATION: 201500843

LOC: 912 12TH
WILMETTE

PROPERTY ID: 05273200090000

OWNER: LIEBERMAN, MORTON A.

CONTRACTOR: PETER CONSTRUCTION CO.

847-251-6260

TRADESMAN: PETER CONSTRUCTION CO.

REQUEST BY: PETER

847-476-0070

call 1 hr before

PROJ DESC: REMOVAL OF EXISTING STEPS/STOOP AND REPLACEMENT WITH NEW
WORK ORDER:

INSPECTOR: ST
REQUESTED: 07/08/15
SCHEDULED: 07/10/15 PM
UNPAID FEES: .00

RESULT: FAIL
PRIORITY: _____
COMPLETED: 7/10/15 1:50 PM
Date Time

MILEAGE: _____ TIME: TRAVEL _____ ONSITE _____

COMMENTS: *① A GRASPABLE HANDRAIL IS REQUIRED ON
AT LEAST ONE SIDE OF THE STAIRWAY, MINIMUM
34" MAXIMUM 38" OVER THE NOSE OF THE TREADS, WHERE
THERE ARE FOUR OR MORE RISERS. THIS STAIRWAY HAS
FIVE RISERS.*

ALL INSPECTIONS:

INSPECTED INSPECTOR RESULT
JN

INSP DESCRIPTION
B015 BASE - WALKWAY

Printed by John Norman

INSPECTION FIELD SHEET

07/09/15
15:29:43

INSPECTION: 212922 FRAMING ROUGH

PERMIT:
STATUS:

APPLICATION: 201403162

LOC: 1242 WILMETTE
WILMETTE

PROPERTY ID: 05341090190000

OWNER: WILMETTE PUBLIC LIBRARY
847-256-5025

CONTRACTOR: FREDERICK QUINN CORPORATION
630-628-8500

REQUEST BY: JEFF
630-442-4463

PROJ DESC: RENOVATION INTERIOR REMODEL
WORK ORDER:

INSPECTOR: ST
REQUESTED: 07/08/15
SCHEDULED: 07/10/15 AM
UNPAID FEES: .00

RESULT:
PRIORITY:
COMPLETED:

PASSED WITH COMMENTS BELOW:

Date Time

MILEAGE:

TIME: TRAVEL ONSITE

COMMENTS:

SECOND AND THIRD FLOORS

① MECHANICAL + ELECTRICAL INSPECTIONS ARE NOT COMPLETED + PASSED AT THIS TIME.
② THERE IS A CHANGE IN ROOM 318 THAT NEEDS TO BE SUBMITTED TO THE VILLAGE.
③ FIREPROOFING MATERIAL HAS BEEN KNOCKED OFF OF THE STEEL IN A NUMBER OF AREAS AND NEEDS TO BE CORRECTED.

ALL INSPECTIONS:

INSPECTED	INSPECTOR	RESULT	INSP	DESCRIPTION
03/24/15	JN	PASSED	B065	FRAMING ROUGH
3RD FL BATHROOMS OK TO DRYWALL				
03/30/15	JN	PASS COMTS	B065	FRAMING ROUGH
2ND FLOOR				
OK TO DRYWALL SOFFETS				
04/07/15	JN	PASSED	B075	ELECTRICAL ROUGH
CEILING LIGHTING ON 2ND FLOOR				
ABOVE CEILING OK TO INSTALL DRYWALL				
05/14/15	JN	PASSED	B075	ELECTRICAL ROUGH
ABOVE CELING				
FOR 2ND AND 3RD FL MAIN ROOMS				
OK TO INSTALL CEILING TILES				
06/02/15	JN	PASSED	B075	ELECTRICAL ROUGH
OVER-HEAD LIGHTING				
03/24/15	JN	PASSED	B075	ELECTRICAL ROUGH
	JN		B075	ELECTRICAL ROUGH
	JN		B080	MECHANICAL ROUGH
03/18/15	MNO	PASSED	B085	PLUMBING ROUGH
07/08/15	MNO	PASSED	B085	PLUMBING ROUGH
03/20/15	MNO	PASSED	B086	REINSPECT PLUMBING ROUGH

Printed by John Norman

INSPECTION FIELD SHEET

07/09/15
15:29:43

INSPECTION: 202873

FRAMING ROUGH

PERMIT: 83636

STATUS: ISSUED 05/14/15

APPLICATION: 201402982

LOC: 1025 GREENWOOD
WILMETTE

PROPERTY ID: 05273120060000

OWNER: VIVEK & ANNE BOMMI

847-920-5158

CONTRACTOR: VIVEK & ANNE BOMMI

847-920-5158

REQUEST BY: KEVIN

847/529-3438

PROJ DESC: MUD ROOM AND REAR DECK ADDITION

WORK ORDER:

INSPECTOR: ST

REQUESTED: 07/06/15

SCHEDULED: 07/10/15 AM

UNPAID FEES: .00

RESULT:

PRIORITY:

COMPLETED:

PASS WITH COMMENTS

7/10/15 9:45 AM
Date Time

MILEAGE:

TIME: TRAVEL

ONSITE

COMMENTS: 1) THERE IS AN EXISTING WINDOW IN THE NEW STAIRWAY THAT DOES NOT APPEAR TO BE SAFETY GLAZING (NO MARKING ON GLASS CAN BE FOUND). NO NOTES ARE ON THE PLANS FOR SAFETY GLAZING. THE CONTRACTOR KEVIN STATES THE WINDOW IS BEING REMOVED.
2) THE EXTERIOR DECK JOIST HANGERS NAILS ARE REQUIRED TO BE

ALL INSPECTIONS:

06/01/15 JN PASSED
REBAR TIED IN PLACE
OK TO POUR CONCRETE

JN
JN
06/04/15 JN PASSED

WALLS BRACED WITH REBAR TIED IN PLACE
OK TO POUR CONCRETE

JN
JN
JN
JN
JN
JN
JN
JN
JN
JN
JN
JN

INSP DESCRIPTION
B025 FOOTING

B030 TRENCH
B035 PIERS
B040 FOUNDATION

B045 BASEMENT FLOOR
B050 GARAGE FLOOR/SLAB
B060 BACKFILL
B067 BUILDING WRAPS
B068 WINDOWS AND DOORS
B070 MASONRY/FIREPLACE ROUGH
B072 OUTSIDE COMBUSTION AIR
B075 ELECTRICAL ROUGH
B077 LIGHTING LAYOUT
B080 MECHANICAL ROUGH
B082 INT AND EXT DAMPERS
B115 INSULATION
B117 PIPING INSULATION

HOT-DIPPED GALVANIZED
OR STAINLESS OR OTHER
MATERIAL AS ALLOWED
IN THE CODE. SOME
OF THE NAILS ARE
NOT COMPLIANT.
CHECK ON LATER
INSPECTION.

Printed by John Norman

INSPECTION FIELD SHEET

07/16/15
15:21:21

INSPECTION: 211593 FRAMING ROUGH

PERMIT: 84487
STATUS: ISSUED 07/06/15
APPLICATION: 201501199

LOC: 2145 GREENWOOD
ACTIVE PIN FOR PERMITTING
WILMETTE

PROPERTY ID: 05283070130000

OWNER: MAGNER, JACQUELINE
CELL: 847-902-9395
CONTRACTOR: CHESTER CONSTRUCTION GROUP
847-758-1000 847-998-8324
MAGNER, JACQUELINE
CELL: 847-902-9395
REQUEST BY: MIKE
224/619-6272

PROJ DESC: REMODEL EXISTING BASEMENT
WORK ORDER:

INSPECTOR: ST
REQUESTED: 07/14/15
SCHEDULED: 07/17/15 AM
UNPAID FEES: .00

RESULT: PASS
PRIORITY:
COMPLETED: 7/17/15
Date Time

MILEAGE: TIME: TRAVEL ONSITE

COMMENTS:

* ADD INSULATION INSPECTION
PASS - SMALL PORTION OF EXTERIOR
WALL OPENED TO CORRECT ELECTRICAL
SYSTEM GROUND TO WATER PIPE
NEW INSULATION INSTALLED

ALL INSPECTIONS:

INSPECTED	INSPECTOR	RESULT	INSP	DESCRIPTION
JN			B045	BASEMENT FLOOR
JN			B070	MASONRY/FIREPLACE ROUGH
ST			B075	ELECTRICAL ROUGH
ST			B080	MECHANICAL ROUGH
MNO			B085	PLUMBING ROUGH
JN			B105	ELECTRICAL SERVICE
JN			B115	INSULATION
JN			B125	CONSTRUCTION FINAL
JN			B130	ELECTRICAL FINAL
JN			B135	MECHANICAL FINAL
MNO			B140	PLUMBING FINAL

INSPECTION FIELD SHEET
Printed by John Norman
INSPECTION: 211810 FRAMING ROUGH
LOC: 816 GREENLEAF WILMETTE
PROPERTY ID: 05342090120000
OWNER: FIRST PRESBYTERIAN CHURCH
847-256-3010
CONTRACTOR: EDGEBROOK CONSTRUCTION
(773) 763-6784
REQUEST BY: BILL
773/593-8884
PROJ DESC: REMODEL BATHROOM, UPGRADE ELECTRICAL SERVICE TO 200 AMP
WORK ORDER:
PERMIT: 84335
STATUS: ISSUED 06/26/15
APPLICATION: 201501226
07/16/15
15:21:21

INSPECTOR: ST
REQUESTED: 07/14/15
SCHEDULED: 07/17/15 am
UNPAID FEES: .00

RESULT: FAIL
PRIORITY:
COMPLETED: 7/17/15 11:50am
Date Time

MILEAGE: TIME: TRAVEL ONSITE

COMMENTS: (1) PLUMBING WALL: NEED STUD SHOES FOR OVERBORED FRAMING
(2) FLOOR JOIST UNDER TUB BY DRAIN; REPAIR WITH SISTERED MEMBER WITH ADHESIVE & NAILS TO BRIDGE THE NOTCHED JOIST.
(3) NEED FIRE BLOCKING AT EXTERIOR WALL (BALLOON FRAMED)

ALL INSPECTIONS:

INSPECTED	INSPECTOR	RESULT
JN		
JN		
ST		
JN		
MNO		
JN		
JN		
JN		
JN		
JN		
MNO		

INSP	DESCRIPTION
B045	BASEMENT FLOOR
B070	MASONRY/FIREPLACE ROUGH AND IN AREA
B075	ELECTRICAL ROUGH
B080	MECHANICAL ROUGH UNDER NEW
B085	PLUMBING ROUGH
B105	ELECTRICAL SERVICE TOILET AND
B115	INSULATION
B125	CONSTRUCTION FINAL AT TOP PLATE
B130	ELECTRICAL FINAL
B135	MECHANICAL FINAL IN THE S. W.
B140	PLUMBING FINAL CORNER,

~~201400456~~
~~7/24/15~~
~~15:18:40~~

Printed by John Norman INSPECTION FIELD SHEET 07/23/15
15:18:40

INSPECTION: 189514 DRAIN TILE PERMIT:
STATUS:
APPLICATION: 201400456

LOC: 921 CAMBRIDGE
WILMETTE

PROPERTY ID: 05283150140000

OWNER: RADEK FIALA
708-203-9191

CONTRACTOR:

REQUEST BY: CHRIS
224/522-9382

PROJ DESC: SINGLE FAMILY RESIDENCE NEW CONSTRUCTION
WORK ORDER:

INSPECTOR: ST RESULT: PASS DRAIN TILE ONLY
REQUESTED: 07/21/15 PRIORITY:
SCHEDULED: 07/24/15 AM COMPLETED: 7/24/15
UNPAID FEES: .00 Date Time

MILEAGE: TIME: TRAVEL ONSITE

COMMENTS: Talked to Leo at Village of Wilmette
Requester Chris wanted Backfill which would
include the Drain tile inspection.
* BACKFILL INSPECTION NOT APPROVED BECAUSE FOUNDATION MORE
THAN 4FT DEEP. FOUNDATION WALLS ARE NOT BRACED AND FIRST
ALL INSPECTIONS:
INSPECTED INSPECTOR RESULT INSP DESCRIPTION
JN B010 BASE - DRIVEWAY
JN B015 BASE - WALKWAY
JN B020 BASE - PATIO
07/07/15 JN PASSED B025 FOOTING
PUMP ON SITE FOR WATER IN FOOTING
JUMPS IN PLACE
OK TO POUR CONCRETE
JN B030 TRENCH
JN B035 PIERS
07/14/15 JN PASSED B040 FOUNDATION
PRE-POUR
WALLS BRACED AND REBAR TIED IN PLACE
OK TO POUR CONCRETE
JN B045 BASEMENT FLOOR
JN B050 GARAGE FLOOR/SLAB
JN B060 BACKFILL
JN B065 FRAMING ROUGH
JN B067 BUILDING WRAPS
JN B068 WINDOWS AND DOORS
JN B070 MASONRY/FIREPLACE ROUGH
JN B072 OUTSIDE COMBUSTION AIR

FLOOR DECK IS NOT FRAMED,
EITHER IS REQUIRED
BY IRC BEFORE
BACKFILL CAN
BE PASSED.

Printed by John Norman

INSPECTION FIELD SHEET

07/23/15
15:18:40

INSPECTION: 206705 ELECTRICAL FINAL

PERMIT: 82704

STATUS: ISSUED 03/24/15

APPLICATION: 201500212

LOC: 111 LAWDALE
WILMETTE

PROPERTY ID: 05334000880000

OWNER: SCHLACHTER, DAVID & ANNE

CONTRACTOR: MARCIN KOCIAKOWSKI ELECTRIC
773-744-3600

TRADESMAN: MARCIN KOCIAKOWSKI

REQUEST BY: MARK
773/490-9806

PROJ DESC: REMODEL KITCHEN
WORK ORDER:

INSPECTOR: ST
REQUESTED: 07/21/15
SCHEDULED: 07/24/15 AM
UNPAID FEES: .00

RESULT: FAIL
PRIORITY:
COMPLETED: 7/24/15
Date Time

MILEAGE: TIME: TRAVEL ONSITE

COMMENTS: ① THE GFCI TESTER IS INDICATING THAT THE HOT/GROUND ARE REVERSE FOR RECEPTACLES LEFT OF THE SINK.
② A GFCI PROTECTED RECEPTACLE IS REQUIRED FOR COUNTER AS TO THE RIGHT OF THE REFRIGERATOR
③ THE TWO LOWER LEFT CIRCUIT BREAKERS IN THE PANEL ARE NOT MARKED WITH MANUFACTURERS NAME. CONFIRM THAT THE CIRCUIT BREAKERS ARE LISTED FOR USE IN THIS SIEMENS PANEL.

ALL INSPECTIONS:

INSPECTED	INSPECTOR	RESULT	INSP	DESCRIPTION
04/02/15	JN	PASSED	B065	FRAMING ROUGH
OK TO INSULATE				
04/02/15	JN	PASSED	B075	ELECTRICAL ROUGH
MARK 773/490-9806				
ADD HARD-WIRED S/D AND C/O AT 1ST FL				
04/02/15	JN	PASSED	B080	MECHANICAL ROUGH
04/02/15	MNO	PASSED	B085	PLUMBING ROUGH
04/06/15	JN	PASSED	B115	INSULATION
OK TO DRYWALL				
ST			B125	CONSTRUCTION FINAL
ST			B135	MECHANICAL FINAL
MNO			B140	PLUMBING FINAL

VIOLATIONS:
DATE STATUS DEPT VIOLATIONS
11/10/10 CLOSED 180 NO PERMIT

④ NOTE: THE ELECTRIC PANEL IS REQUIRED TO HAVE THE BREAKER CIRCUITS LABELED OR PANEL SCHEDULE.

Printed by John Norman

INSPECTION FIELD SHEET

07/23/15
15:18:40

INSPECTION: 211081

FOOTING

PERMIT: 84756

STATUS: ISSUED 07/20/15

APPLICATION: 201501142

LOC: 218 10TH
WILMETTE

PROPERTY ID: 05344000110000

OWNER: RONAN, PATRICK

CONTRACTOR: WAL-MOR GENERAL & MECHANICAL PLUMB
773-785-7667
RONAN, PATRICK

REQUEST BY: LUIS
262/620-5973

PROJ DESC: NEW SINGLE FAMILY HOME
WORK ORDER:

INSPECTOR: ST
REQUESTED: 07/22/15
SCHEDULED: 07/24/15 PM
UNPAID FEES: .00

RESULT: FAIL
PRIORITY:
COMPLETED: _____
Date Time

MILEAGE: _____ TIME: TRAVEL _____ ONSITE _____

COMMENTS: ① PLANS SHOW FOOTINGS SHOULD BE 24" WIDE.
FORMS SET AT 20" WIDE.

② PIERS ARE NOT FRAMED.

③ REBAR IS SHOWN ON PLANS. NO REBAR IS IN PLACE
AND NO REBAR ON SITE.

ALL INSPECTIONS:

INSPECTED	INSPECTOR	RESULT	INSP	DESCRIPTION
JN			B010	BASE - DRIVEWAY
JN			B015	BASE - WALKWAY
JN			B020	BASE - PATIO
JN			B030	TRENCH
JN			B035	PIERS
JN			B040	FOUNDATION
JN			B045	BASEMENT FLOOR
JN			B050	GARAGE FLOOR/SLAB
JN			B055	DRAIN TILE
JN			B060	BACKFILL
JN			B065	FRAMING ROUGH
JN			B067	BUILDING WRAPS
JN			B068	WINDOWS AND DOORS
JN			B070	MASONRY/FIREPLACE ROUGH
JN			B072	OUTSIDE COMBUSTION AIR
JN			B075	ELECTRICAL ROUGH
JN			B077	LIGHTING LAYOUT
JN			B080	MECHANICAL ROUGH
JN			B082	INT AND EXT DAMPERS

CODE ENFORCEMENT:
THE SILT FENCE
IS NOT DUG IN.
SILT FENCE IS
FALLING DUE TO
MATERIALS.
FENCE AT
STREET NOT
SECURE AGAINST
ENTRY.



**Development Department
Inspectional Services**

Inspection Field Sheet

Permit Address: 1821 ADMIRAL CT
Inspection Number: 114787

Date: 09/15/2015
Inspection Type: REINSPECT ROUGH PLUMBING
Inspection Result: NOT APPROVED

Comments: Demo'd Pipe has not been removed. Unable to see capped dead ends.
Please make sure the dead ends do not exceed 2'. Please have floor exposed in all areas
that pipe has been demo'd and capped.

Inspector: JIM KEMPER

Received By

1225 Waukegan Road
Glenview, IL 60025

Phone: (847) 904-4320
Fax: (847) 724-1752

Page 1 of 1

CITY OF EVANSTON
PLAN REVIEW

925 Brown Ave
2nd floor addition/remodel

9/22/14
Page 1 of 3

DOCUMENTS

We have reviewed the following documents: Sheets 1 through 6 dated Aug 12, 2014.

Notice: Failure to identify a Code Violation during the review of plans does not give the Permit Applicant the right to violate the Code. The final installation must be in accordance with all applicable codes.

GENERAL COMMENTS

No. Comments

G1 Please bubble any changes to the drawings. Submit an item-by-item response to the comments.

END OF GENERAL COMMENTS

ARCHITECTURAL/STRUCTURAL COMMENTS

2012 INTERNATIONAL RESIDENTIAL CODE

- A-1 Sheet 1 List codes with 'City of Evanston amendments'.
- A-2 Sheet 1—List Plumbing Code as State of Illinois Plumbing Code.
- A-3 Sheet 6—The existing footing/foundation must be analyzed for adequacy to support the second story addition. Expose the footing in at least one location, provide pictures, note existing materials and dimensions, and note determination of adequacy by design professional.
- A-4 Sheet 6 Provide connection detail for sistering I-joists to existing ceiling joists. How do ceiling joists at 16" o.c. get sistered to I-joists at 12" o.c.?
- A-5 Provide load calculation for floor joists. Are the I-joists adequate by themselves, or does the design rely on the sistering to the existing 2x8 ceiling joists?
- A-6 Provide framing detail around stairs. Show how the 2nd floor loads transfer to the foundation. If relying on 1st floor 2x10 floor joists, interior footings, and/or steel beam provide a calculation showing they are adequate.
- A-7 Provide framing detail for LVLs in foyer and through dining room. Are the two eastmost spans intended to span the entire house front to back, or is a mid-span column intended? Provide calculations for the LVLs and existing interior structural members used to support them.

CITY OF EVANSTON
PLAN REVIEW

925 Brown Ave
2nd floor addition/remodel

9/22/14
Page 2 of 3

- A-8 Sheet 3—Label all windows that meet emergency escape and rescue requirements. Minimum one per sleeping room.
- A-9 Sheet 6—Clarify existing 1st floor exterior wall construction. It appears the 2nd floor cantilever is bearing on the brick veneer—provide details or explanation showing that this will not happen.
- A-10 Show columns for each ridge beam (they appear to be in the middle of rooms).
- A-11 How are the top end of the valley members supported? Provide sizes and calculations for the valley members.
- A-12 Indicate the size of headers, particularly those supporting ridge beams.
- A-13 Provide framing detail for tray ceiling in Master bedroom.
- A-14 Provide detail/notes explaining how new porch foundation is tied into existing foundation. Such details as dowel size, spacing, embedment depth, epoxy type, etc. shall be included.
- A-15 Show collar ties or ridge straps in the upper third of attic per IRC 802.3.1.
- A-16 Sheet 6—Exterior wall specifications list R-19 insulation, but detail says R-21. Correct for consistency.
- A-17 Show the Master bathroom window as safety glazed.
- A-18 Provide U-factor of new windows on plans. (0.32 or better required).
- A-19 Show handrail on the stairs.

END OF ARCHITECTURAL/STRUCTURAL COMMENTS

MECHANICAL COMMENTS

2012 INTERNATIONAL MECHANICAL CODE

- M-1 Show compliant access path for access to furnace in attic.
- M-2 Show how the water line to the humidifier will be protected from freezing.
- M-3 Provide gas one-line diagram suitable to handle new gas load.
- M-4 List insulation values for duct work in unconditioned attics.
- M-5 Note that the relocated, existing equipment must maintain proper working clearances and distances from combustible construction per the manufacturer's specs and code.

END OF MECHANICAL COMMENTS

CITY OF EVANSTON
PLAN REVIEW

925 Brown Ave
2nd floor addition/remodel

9/22/14
Page 3 of 3

PLUMBING COMMENTS

ILLINOIS PLUMBING CODE

P-1 Provide water service fixture unit calculation. Indicate if 1" water service and meter is existing or is intended to be upgraded.

END OF PLUMBING COMMENTS

ELECTRICAL COMMENTS

2011 NATIONAL ELECTRICAL CODE

E-1 Show location of electric service panel. Is the panel existing to remain, or being upgraded?

E-2 Provide electrical load calculation.

E-3 Note the location of the electrical riser pipe and utility drop attachment. Note if any reworking is intended.

END OF ELECTRICAL COMMENTS

Review By: Steve Touloumis, SAFEbuilt

If you have any questions about this review, please contact me at 224 277 1073 or
stouloumis@safebuilt.com.

G. Start Date

SAFEbuilt has an available start date of November 02, 2015.

H. Point of Contact

The point of contact has been emailed to the following email address: mrysavy@bensenville.il.us